

Phase 2 Environmental Assessment of the Government Hill Wireless Station

Prepared by

EHS Alaska, Inc.

and

Shannon & Wilson, Inc.

December 11, 1997

**Incorporated by reference as
Appendix E to the Government Hill Wireless Station
Historic Structure Report (HSR)**

This page intentionally left blank.

**PHASE 2 ENVIRONMENTAL SITE ASSESSMENT
GOVERNMENT HILL WIRELESS STATION
132/140 EAST MANOR AVENUE
ANCHORAGE, ALASKA**

**Prepared for the
U.S. Department of the Interior
General Services Administration
And
The United States Geological Survey**

Prepared by



**ENGINEERING, HEALTH & SAFETY CONSULTANTS
10928 EAGLE RIVER ROAD, SUITE 202
EAGLE RIVER, ALASKA 99577-8052
694-1383 • 694-1382 fax • 1-800-340-3022**

and

**Shannon & Wilson, Inc.
5430 Fairbanks Street, Suite 3
Anchorage, Alaska 99518**

December 11, 1997

TABLE OF CONTENTS

| | |
|---|----|
| EXECUTIVE SUMMARY | i |
| Part 1 SURVEY INFORMATION | |
| 1.01 Site Complex Description | 1 |
| 1.02 Structural Concerns | 1 |
| 1.03 Survey Overview | 2 |
| 1.04 Analysis Overview | 2 |
| 1.05 Areas Not Accessed by this Survey. | 2 |
| Part 2 BUILDING SURVEYS | |
| 2.01 Description of Building 1, "Tee" Shaped Building | 3 |
| 2.02 Asbestos Survey Results, Building 1 | 4 |
| 2.03 Lead Survey Results, Building 1 | 6 |
| 2.04 Chemical Hazards Survey Results, Building 1 | 7 |
| 2.05 Description of Building 2, North Building | 7 |
| 2.06 Asbestos Survey Results, Building 2 | 8 |
| 2.07 Lead Survey Results, Building 2 | 9 |
| 2.08 Chemical Hazards Survey Results, Building 2 | 10 |
| 2.09 Description of Building 3, Wireless Building | 10 |
| 2.10 Asbestos Survey Results, Building 3 | 11 |
| 2.11 Lead Survey Results, Building 3 | 14 |
| 2.12 Chemical Hazards Survey Results, Building 3 | 15 |
| Part 3 CONCLUSIONS AND RECOMMENDATIONS | |
| 3.01 Asbestos | 15 |
| 3.02 Lead | 16 |
| 3.03 Chemical Hazards | 17 |
| Part 4 REGULATIONS | |
| 4.01 Asbestos | 17 |
| 4.02 Lead | 18 |
| 4.03 Chemical Hazards | 18 |

APPENDICES

| | |
|------------|---|
| APPENDIX A | ASBESTOS FIELD DATA SHEETS AND LABORATORY REPORTS |
| APPENDIX B | LEAD FIELD DATA SHEETS AND LABORATORY REPORTS |
| APPENDIX C | FLOOR PLANS WITH BULK SAMPLE LOCATIONS |
| APPENDIX D | PHOTOGRAPHS OF POTENTIALLY HAZARDOUS MATERIALS |

EXECUTIVE SUMMARY

PHASE 2 ENVIRONMENTAL SITE ASSESSMENT GOVERNMENT HILL WIRELESS STATION 132/140 EAST MANOR AVENUE ANCHORAGE, ALASKA

INTRODUCTION

The Government Hill Wireless Station site and buildings located at 132/140 East Manor Avenue, in Anchorage, Alaska, were surveyed as part of a Phase 2 Environmental Site Assessment. The hazardous materials survey of the buildings was conducted by EHS-Alaska, Inc. The tank removal and subsurface soil investigation was conducted by Shannon & Wilson, Inc. The attached report contains the full details of the Phase 2 Environmental Site Assessment.

The floor structure has failed in portions of all three buildings and further rapid deterioration of the floor structure is anticipated due to the wet condition of the crawl spaces. The roofing at the chimneys of Buildings 1 and 2 was damaged by snow movement, and all three buildings are being damaged by water infiltration. Repair work to the structures will require disturbance of hazardous materials. A specific survey including destructive investigation for hazardous materials should be performed as part of the design work for any future repair work.

HAZARDOUS MATERIALS INSIDE THE BUILDINGS

Lead-containing paints were found on the interior and exterior of each building.

Fluorescent light ballasts in each building were found to contain polychlorinated biphenyls (PCBs). Other chemical hazards include the following mercury containing items: switches, thermostats and fluorescent light fixture tubes.

Asbestos-containing materials (ACM) were found in each building, typically including joint compound of the wall and ceiling finishes, flooring materials, cement asbestos board, roofing materials, and pipe insulation. The majority of the ACM was non-friable and not likely to release asbestos fibers unless disturbed. Friable ACM materials (considered to be more hazardous because they can be crushed and reduced to powder by hand pressure) were found in each building, but in smaller quantities.

The following non-friable asbestos-containing materials were found in Building #1: Red 12"x12" floor tile, cement asbestos board, wire insulation, sheet vinyl flooring, and roofing materials. The friable ACM found in Building 1 included pipe insulation in the crawl space of the west wing, furnace gaskets and furnace refractory insulation.

The following non-friable asbestos-containing materials were found in Building #2: Joint compound of gypsum wall board walls and ceilings, dark brown 9"x9" floor tile, cement asbestos

board, and roofing materials. The friable ACM found in Building 2 included pipe insulation in the crawl space, furnace gaskets, furnace refractory insulation and loose asbestos paper in the attic.

The following non-friable asbestos-containing materials were found in Building #3: Joint compound of cellulose board walls and ceilings in north addition, joint compound of gypsum wall board walls and ceilings in south addition, cement asbestos board, and roofing materials. The friable ACM found in Building 3 included furnace and boiler gaskets, furnace and boiler refractory insulation, and pipe insulation in the basement and crawl space.

SUBSURFACE SITE INVESTIGATION AND TANK REMOVAL

Four soil borings were drilled in July and August 1997 at locations that were chosen to assess the potential impact on the property by the sources identified in the Phase 1 Environmental Site Assessment. Three borings were approximately 17 feet deep and one boring was extended to 39.5 feet, approximately 1 foot below the groundwater level. The three shallow borings did not contain concentrations of petroleum hydrocarbons or hazardous substances exceeding the applicable cleanup criteria. The deep boring contained concentrations of Diesel Range Organics (DRO) and methylene chloride above the applicable federal and state cleanup criteria in the soil and the groundwater at the groundwater level. The presence of contamination in the soil at the groundwater depth as well as in the groundwater raised the cleanup criteria for the site to Category A, (the most restrictive) according to Alaska Department of Environmental Conservation (ADEC) guidelines.

A dry well located at the north end of Building #1 (previously used as a garage) was investigated and contaminated soil was located at a depth of about 3 feet and likely to be deeper to an unknown depth. The concentrations of DRO and Residual Range Organics (RRO) were above the applicable cleanup criteria. The concentrations of polychlorinated biphenyls (PCBs) and lead in soil at the dry well were below the applicable cleanup criteria, but will greatly impact the cost of cleanup and disposal.

Two 500 gallon and one 300 gallon underground storage tanks (USTs) were removed in September 1997 from the site. Heating oil was removed from each of the tanks prior to tank removal. Samples from undisturbed soil surrounding each of the tanks were above the applicable cleanup criteria for DRO, and two samples from the soil around Tank 3 contained concentrations of benzene which were above the applicable cleanup criteria.

Refer to the attached Phase II Site Assessment report produced by Shannon & Wilson for more information on the tank removal and subsurface soil investigation. Due to the presence of documented contamination at the site, and most importantly in the groundwater, the Alaska Department of Environmental Conservation requires immediate notification of these results. At your request we will submit a copy of the Phase II report to the appropriate ADEC representative.

**HAZARDOUS MATERIALS SURVEY REPORT
GOVERNMENT HILL WIRELESS STATION
132/140 EAST MANOR AVENUE
ANCHORAGE, ALASKA**

PART 1, SURVEY INFORMATION

The Government Hill Wireless Station facilities located at 132/140 East Manor Avenue, in Anchorage, Alaska, was surveyed for the presence of asbestos-containing materials (ACM), lead-containing materials (LCM), and Chemical Hazards including Polychlorinated Biphenyls (PCBs). The inspection was conducted in September 1997 by Robert French of EHS-Alaska, Inc.

1.01 SITE COMPLEX DESCRIPTION

The Government Hill Wireless Station was originally constructed in 1917 by the Alaska Engineering Commission which is now the Alaska Railroad Corporation. The Wireless Station is listed on the Alaska Heritage Resources Survey and has been nominated for the National Register of Historic Places (NRHP). The Wireless Station served as the only communication link between Anchorage and the outside world until 1931. The Wireless Station was transferred to the Alaska Communication System in 1936, to the U.S. Army in 1952, and to the U.S. Air Force in 1962. Following the sale of the Alaska Communication System to RCA Alaska Communications, Inc. (RCA/Alascom) the site was leased to RCA from 1971 to 1976. The property was declared excess to the General Services Administration (GSA) in 1976 and GSA transferred the property to the United States Geological Survey (USGS) in 1976. The USGS occupied the buildings until 1985, and used it primarily as cold storage for drilling cores until 1994. The construction dates for the three buildings and their additions are in conflict from several different sources. The buildings are described separately below in Part 2.

1.02 STRUCTURAL CONCERNS

The crawl spaces of the buildings were typically shallow, unventilated and had dirt floors. Because the buildings have not been heated for the past decade or more, and because of additional stresses from storage of heavy drill cores of rock samples, portions of the floor structures are in advanced stages of decay caused by "dry-rot". The damage is limited, with areas in each building having failed. However, there is obvious evidence of further water damage presently occurring. There was water soaked subflooring in Building 2 with condensation and advanced visible fungal growth in the crawl spaces of all three buildings.

The lack of crawl space venting and water infiltration will require immediate attention to halt the on going deterioration. If deterioration is allowed to continue at it's present rate, more costly structural repairs may be required.

1.03 SURVEY OVERVIEW

The survey included comprehensive but limited bulk sampling of potentially hazardous materials. Because of the historic nature of the structures and the danger and difficulty of access, not all materials present in the building were sampled. Hazardous materials may exist which were not sampled. See part 1.05 below for more information on areas not surveyed.

The survey included sampling of materials suspected of containing asbestos, and sampling of painted materials to see if LCM was present. Nearly all surfaces in the buildings were coated with paint. The painted surfaces sampled included gypsum wall board, wood and metal surfaces.

1.04 ANALYSIS OVERVIEW

The suspected asbestos-containing materials were subjected to analysis using polarized light microscopy and dispersion staining (EPA method 600/M4-82-020). The asbestos content was reported as an estimated weight percentage. Asbestos samples were analyzed by RJ Lee Group, Inc. of San Leandro California, and Solar Environmental Services, Inc. of Anchorage, Alaska. Both laboratories are accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) for bulk asbestos analysis. Only materials containing more than 1% total asbestos were classified as "asbestos-containing" based on Environmental Protection Agency (EPA) and Occupational Safety and Health Administration (OSHA) criteria.

The suspected lead-containing materials were subjected to analysis using digestion and atomic absorption (EPA method 7420). The lead content was reported as a weight percentage. Lead samples were analyzed by RJ Lee Group, Inc., of Monroeville Pennsylvania, an American Industrial Hygiene Association (AIHA) accredited laboratory.

1.05 AREAS NOT ACCESSED BY THIS SURVEY

Portions of the crawl spaces were not accessed during this survey because of the danger posed by the rotting timbers, and extremely limited space. The materials in those areas were assumed to be similar to the remainder of the surveyed areas. Because the survey included only limited destructive testing, materials inside walls, and ceiling/roof structures were typically not accessed by this survey.

The buildings had similar aluminum roofing installed within the past decade to prevent further deterioration of the building structures. That aluminum roofing had asbestos-containing sealants applied at penetrations. In all three buildings, the metal roofing had been installed over the existing roofing. Representative samples of the roofing materials were taken, however, not all areas of the existing roofing were accessible for inspection.

PART 2 BUILDING SURVEYS

2.01 DESCRIPTION OF BUILDING 1, "TEE SHAPED" BUILDING

The "Tee Shaped" building was reported to have been constructed in 1943 by the Black-Smith & Richards Appraisal Report. The 1990 Department of the Army Finding and Determination of Eligibility report listed the 3 buildings as having been constructed in 1930, 1934 and 1949, with no indication of which building was constructed at which time. The 1983 nomination to the NRHP listed the structure as being built prior to 1964. The presence of exterior siding between the west wing and the long section of the "Tee" and the changed structure in the attic and crawl space of the west wing indicate that the building may have been constructed in three phases. The initial phase appears to be the central section of the west wing, with the long garage and office section to the east and 18'-6" addition to the west being added prior to 1950. The concrete stem walls and slab with a "dry-well" to the north of the "Tee building" may indicate the presence of a carport or similar structure that has since been removed.

The long section of the "Tee" had poured concrete walls that extend up 4 feet from the concrete slab floor. The south portion of this building was renovated approximately in the early 1960's (based on millwork used) and had a wooden floor raised approximately 8 inches above the concrete slab, lowered gypsum board ceiling, and furred and insulated walls. The wood flooring in the south office had been covered with an asbestos-containing "peel-n-stick" type flooring. The east portion of the structure did not have any apparent structural damage, except where the roof thimble of the building furnace had been damaged by sliding snow. The joint compound of the south room in the long section of the "Tee" contained asbestos. The garage room of the north wing, did not have joint compound applied to the gypsum board. The joint compound of the furnace room did not contain asbestos.

The western wing of the building served most recently as a kitchen and service area and had gypsum board walls and ceilings, with asbestos-containing sheet vinyl flooring. The top layers of flooring may have concealed additional layers of flooring, as broken bits of vinyl asbestos tile were noted in the crawl space. The central area of the west wing had a dirt floored crawl space that was shallower than the west portion of the west wing. Part of the floor structure in the central portion of the west wing had sunk approximately 6 inches. The joint compound of the west wing contained asbestos.

Building 1 had an electric water heater located in the kitchen with exposed bare piping to the sink. The original iron domestic water piping in the central crawl space had been removed and replaced with uninsulated copper piping. There was friable asbestos-containing pipe insulation debris in that crawl space that is assumed to be associated with the removed piping.

Building 1 had been heated by a furnace located near the intersection of the "Tee". Ducts were concealed between the two ceiling surfaces in the south room, exposed below the upper ceiling in the north room, and were located in the attic space of the west wing. The air returned to the furnace through a wall grill. The oil fired furnace had been converted to gas probably at the same time as the other buildings, approximately 1980.

2.02 ASBESTOS SURVEY RESULTS, BUILDING 1

Asbestos field survey data sheets and laboratory reports are included as Appendix A. The drawing in Appendix C shows locations where the asbestos samples were taken. Refer to the field survey data sheets for additional sample information. The following table summarizes the asbestos survey results for Building 1.

| Sample No. | Description/Location | Results |
|------------|--|-----------------------------------|
| GH 997-1 | Gypsum, mud & tape/S office, SE corner. Composite sample reported as <1% Chrysotile. Joint compound contained 2% Chrysotile. | <1% Chrysotile (2% Chrysotile) |
| GH 997-2 | Red brick pattern "self-stick", 12"x12" tile/S office at door | 3 % Chrysotile |
| GH 997-3 | Gypsum, mud & tape/Main S room, NE corner @ furnace room. Composite sample reported as <1% Chrysotile. Joint compound contained 2% Chrysotile. | <1% Chrysotile (2% Chrysotile) |
| GH 997-4 | Cement fiber board/Furnace room, S wall | 40% Chrysotile |
| GH 997-5 | Gypsum, mud & tape/N room @ furnace room | None Detected |
| GH 997-6 | Gypsum/N room, NW corner | None Detected |
| GH 997-7 | Red brick pattern "self-stick" 12"x12" floor tile/S office @ W wall | 4% Chrysotile |
| GH 997-8 | Building paper/Exterior - under siding, SE corner | None Detected |
| GH 997-9 | White, ropy gasket @ furnace/@ burner plate to furnace body | 80% Chrysotile 5% Amosite |
| GH 997-10 | White, waxy wire insul. /@ incand. light on fixture side | 50% Chrysotile |
| GH 997-11 | Rubbery wire insul. /@ incand. light on house side | None Detected |
| GH 997-12 | Red woven wire insul. /@ fluor. light on fixture side | None Detected |
| GH 997-13 | Gypsum, mud & tape/Behind door in toilet, W wing. Composite sample reported as <1% Chrysotile. Joint compound contained 2% Chrysotile. | <1% Chrysotile (2% Chrysotile) |
| GH 997-14 | Light brown 1/4" chips SV /@ floor hatch in toilet, W wing | 35% Chrysotile |
| GH 997-15 | Brown cove base mastic/Behind door in toilet, W wing | None Detected |
| GH 997-16 | Tar paper underlayment/Between T+G & lap boards | None Detected |
| GH 997-17 | White cardbd. pipe insul./In crawl space under toilet | 85% Chrysotile |
| GH 997-18 | Tar paper underlayment/Under toilet @ dry rot | None Detected |
| GH 997-19 | White cardbd. pipe insul. /In crawl space off of pipe | 95% Chrysotile |
| GH 997-20 | Gray, jute backed linoleum/Patch on wall of toilet | None Detected |
| GH 997-21 | Cove base & creamy mastic/W wing kitchen | None Detected |
| GH 997-22 | Light brown 1/4" chip-sheet vinyl/@ hole in floor between west & east rooms, west wing | 35% Chrysotile |
| GH 997-23 | Cove base & creamy brown mastic/Middle room in W wing | None Detected |
| GH 997-24 | Insul. @ incand. light & mastic/Kitchen, W wing | None Detected |
| GH 997-25 | Pink fiberglass ceiling insul. /NW corner, kitchen | None Detected |

| Sample No. | Description/Location | Results |
|------------|---|----------------|
| GH 997-26 | Blown in mixed insul. /NW corner, kitchen | None Detected |
| GH 997-27 | Brown crepe paper ceiling insul. /S side above kitchen | None Detected |
| GH 997-28 | Blown in mixed insul. /Middle above kitchen | None Detected |
| GH 997-29 | Gable end tar paper/W end of attic | None Detected |
| GH 997-30 | Roof tar paper/Above hatch in kitchen | None Detected |
| GH 997-31 | Brown crepe paper duct insul. /Above hatch in kitchen | None Detected |
| GH 997-32 | Red & white floor tile with black mastic/In crawl space below kitchen | 5% Chrysotile |
| GH 997-33 | Roof tar paper/N wing above hatch | None Detected |
| GH 997-34 | Blown in multi colored ceiling insul. /N wing, S of hatch | None Detected |
| GH 997-35 | Blown in multi colored ceiling insul. /N wing, N of hatch | None Detected |
| GH 997-36 | Celotex board ceiling/Above ceiling to S wing | None Detected |
| GH 997-37 | Celotex board ceiling/Above ceiling to S wing | None Detected |
| GH 997-38 | Window caulking/Furnace room window | <1% Chrysotile |
| GH 997-39 | Black & gray roof patch/@ 3" pipe above kitchen | 10% Chrysotile |
| GH 997-40 | Black & silver roofing/Under metal roofing Composite sample contained 1% Chrysotile, Silver layer contained 10% Chrysotile. | 1% Chrysotile |
| GH 997-41 | Black & gray roof patching/@ elec. drop to Bldg. 1 | 15% Chrysotile |
| GH 997-Q1 | Quality control sample to GH 997-2, Red brick pattern "self-stick", 12"x12" tile/S office at door | 10% Chrysotile |
| GH 997-Q2 | Quality control sample to GH 997-8, Building paper/Exterior - under siding, SE corner | None Detected |
| GH 997-Q3 | Quality control sample to GH 997-28, Blown in mixed insul. /Middle above kitchen | None Detected |

The following materials were found to contain asbestos:

| <u>Material</u> | <u>Asbestos content</u> |
|--|------------------------------|
| 1. Red brick pattern "self-stick", 12"x12" floor tile | 4 % Chrysotile |
| 2. Joint compound of gypsum wall board walls and ceiling of south and west wing | 3% Chrysotile |
| 3. Cement asbestos board on walls and ceiling of furnace room | 40 % Chrysotile |
| 4. Gaskets in furnace | 80% Chrysotile 5% Amosite |
| 5. High temperature wire insulation at incandescent light fixtures | 50 % Chrysotile |
| 6. Light brown 1/4" chips sheet vinyl flooring in west wing | 35 % Chrysotile |
| 7. White cardbd. pipe insulation in crawl space | 95 % Chrysotile |
| 8. Red vinyl asbestos tile, found in crawl space, assumed partly removed and concealed under sheet vinyl flooring in west wing | 5 % Chrysotile |
| 9. Roof patching compound on metal roofing | 15 % Chrysotile |

The following materials were found to contain less than 1 percent asbestos:

1. Window caulking of older windows in north wing.

The following materials were assumed to contain asbestos:

1. Sealants on metal roofing.
2. Window caulking of west wing.
3. Concealed roofing materials.
4. Gaskets inside furnace, and concealed furnace refractory insulation.

2.03 LEAD SURVEY RESULTS, BUILDING 1

Lead field survey data sheets and laboratory reports are included as Appendix B. The drawing in Appendix C shows locations where lead samples were taken. Refer to the field survey data sheets for additional sample information. The following table summarizes the lead survey results for Building 1.

| Sample No. | Description/Location | Results, % Lead |
|-------------------|--|------------------------|
| GH 997-L1 | Green paint on gypsum/SE corner of S office | 0.0603 % |
| GH 997-L2 | Red paint, clear varnish on wood/@ floor, entry to S office | 0.178 % |
| GH 997-L3 | Gray & white paint on wood/S room @ rack supports | 0.0718 % |
| GH 997-L4 | White paint on gypsum/N room walls, NW corner | <0.013 % * |
| GH 997-L5 | White paint on gypsum/S room ceiling, NW corner | 0.00514 % |
| GH 997-L6 | Green paint on wood trim/Behind door, W wing toilet | <0.012 % * |
| GH 997-L7 | Green paint on gypsum/Behind door in toilet, W wing | <0.0055 % * |
| GH 997-L8 | Exterior white paint on wood siding/SW corner of W wing | 11.6 % |
| GH 997-L9 | Ext. green trim paint on wood trim/NW corner of W wing | 13.8 % |
| GH 997-L10 | White paint on duct/Above furnace | 7.48 % |
| GH 997-L11 | White & silver paint on duct/@ branch to S wing | 0.459 % |
| GH 997-L12 | White & silver paint with silvery metal/@ joints of branch to S wing | 27.7 % |

* "<" indicates that the amount of lead present was less than the limit of detection for the analysis.

Interior finish materials typically contained detectable quantities of lead. The green paint in the west wing, and the white paint in the north wing contained less lead than the limit of detection for the analysis conducted.

The white and green exterior paints had high concentrations of lead.

Sample L12 appeared to contain solder from the joint of the ductwork, and therefore had a high concentration of lead.

Paints in Building 1 were typically in good condition, with peeling paint noted only in the west wing, and at the furnace chimney due to water leakage.

The following materials were assumed to contain lead, and were not sampled:

1. Solder joints of copper piping.
2. Lead flashing at roof penetrations.
3. Leaded joints of cast iron bell and spigot piping.

2.04 CHEMICAL HAZARDS SURVEY RESULTS, BUILDING 1

All types of fluorescent light fixtures were inspected at random for the presence of Polychlorinated biphenyl (PCB) containing ballasts. None of the light ballasts in Building 1 had "NO PCBs" printed on their labels. Those ballasts are required by law to be assumed to contain PCBs unless they are tested (testing is more expensive than removal). Electrical switches and thermostats commonly contain mercury, as do fluorescent light tubes.

There was a total of 17, four tube fluorescent light fixtures and 1, two tube fluorescent light fixtures in Building 1.

2.05 DESCRIPTION OF BUILDING 2, NORTH BUILDING

The North Building was reported to have been constructed in 1943 by the Black-Smith & Richards Appraisal Report. The 1990 Department of the Army Finding and Determination of Eligibility report listed the 3 buildings as having been constructed in 1930, 1934 and 1949, with no indication of which building was constructed at which time. The 1983 nomination to the NRHP listed the structure as being built prior to 1964.

Building 2 was supported on wood timber pads with wood skirting that extended to the ground at the perimeter. The crawl space was partly ventilated by holes in the perimeter skirting, however the subflooring was saturated with water at the floor hatch in the furnace room. The center of the main room had been raised approximately 8 inches by differential movement. The remaining structure did not have any apparent structural damage, except where the roof thimble of the building furnace had been damaged by sliding snow.

Building 2 had asbestos-containing joint compound on the gypsum board walls and ceilings, with asbestos-containing vinyl tile flooring in the main room. The furnace room and former toilet had an older jute-backed linoleum flooring that did not contain asbestos. There was asbestos-containing pipe insulation on the cold water pipe in the crawl space. This pipe extended vertically out of the crawl space soil into the toilet room directly above. Building 2 did not have any hot water service.

Building 2 had been heated by a furnace located in the southwest furnace room. Uninsulated ducts were located in the attic space. The air returned to the furnace through a wall grill, with an additional air intake from the attic space. The oil fired furnace had been converted to gas

probably at the same time as the other buildings, approximately 1980. The attic was partly insulated with fiberglass and mineral wool insulation. Two sheets of friable asbestos-containing paper were noted in the attic space, and more may have been concealed under the insulation. The previous use of this paper was not apparent, but may have been used as a heat shield.

2.06 ASBESTOS SURVEY RESULTS, BUILDING 2

Asbestos field survey data sheets and laboratory reports are included as Appendix A. The drawing in Appendix C shows locations where the asbestos samples were taken. Refer to the field survey data sheets for additional sample information. The following table summarizes the asbestos survey results for Building 2.

| Sample No. | Description/Location | Results |
|------------|---|-------------------------------------|
| GH 997-42 | Dark brown 9"x9" floor tile w/black mastic/NW corner | 3% Chrysotile |
| GH 997-43 | Gypsum, mud & tape/Center N. wall. Composite sample reported as <1% Chrysotile. Joint compound contained 3% Chrysotile. | <1% Chrysotile (3% Chrysotile) |
| GH 997-44 | Dark brown 9"x9" floor/Center @ hump | 3% Chrysotile |
| GH 997-45 | Gypsum, mud & tape/Outside corner of furnace room. Composite sample reported as <1% Chrysotile. Joint compound contained 3% Chrysotile. | <1% Chrysotile (3% Chrysotile) |
| GH 997-46 | Cement fiber board on wall/Furnace room wall | 40% Chrysotile |
| GH 997-47 | Window caulking/North window | 1% Chrysotile |
| GH 997-48 | Cement fiber board on floor/Under furnace | 45% Chrysotile |
| GH 997-49 | Rope gasket on RA side of furnace/Inside furnace | 90% Chrysotile |
| GH 997-50 | Gypsum, mud & tape/In toilet. Composite sample reported as <1% Chrysotile. Joint compound contained 3% Chrysotile. | <1% Chrysotile (3% Chrysotile) |
| GH 997-51 | Soft gasket @ furnace clean-out/Room side of furnace | 80% Chrysotile |
| GH 997-52 | Grit surfaced tar paper floor underlay/@ floor hatch W side, very wet & soft above | None Detected |
| GH 997-53 | Gray-reddish tar linoleum/@ floor hatch | None Detected |
| GH 997-54 | Grit surfaced tar paper floor underlay/@ floor hatch, E side | None Detected |
| GH 997-55 | Gray-reddish tar linoleum/N of furnace | None Detected |
| GH 997-56 | Dark brown 9"x9" floor tile with light brown mastic/SE area | 3% Chrysotile |
| GH 997-57 | Gray wool ceiling insul. /S side of attic | None Detected |
| GH 997-58 | Grit surfaced roofing with silver coating/south middle of attic, through knot hole. Composite sample reported as <1% Chrysotile, silver layer contained 10 % Chrysotile | <1% Chrysotile (10 % Chrysotile) |
| GH 997-59 | Gray wool ceiling insul. /Middle of attic | None Detected |
| GH 997-60 | Gray wool ceiling insul. /N side of attic | None Detected |
| GH 997-61 | Tar paper @ siding/N side gable @ hatch | None Detected |

| Sample No. | Description/Location | Results |
|------------|---|----------------|
| GH 997-62 | White thin paper/Loose in attic | 95% Chrysotile |
| GH 997-63 | White thin paper/Loose in attic by hatch | 95% Chrysotile |
| GH 997-Q4 | Quality control sample to GH 997-55, Gray-reddish tar linoleum/N of furnace | None Detected |

The following materials were found to contain asbestos:

| <u>Material</u> | <u>Asbestos content</u> |
|---|-------------------------|
| 1. Joint compound of gypsum wall board walls and ceiling | 3% Chrysotile |
| 2. Cement asbestos board on walls and floor of furnace room | 45 % Chrysotile |
| 3. Gaskets at furnace | 90% Chrysotile |
| 4. Window caulking | 1% Chrysotile |
| 5. Dark Brown 9"x9" floor tile | 3% Chrysotile |
| 6. Silver coating on roofing below aluminum roofing | 10% Chrysotile |
| 7. White thin paper, loose in attic, noted in 2 places, may be concealed elsewhere. | 95% Chrysotile |

The following materials were assumed to contain asbestos:

1. Sealants on metal roofing.
2. "Aircell" pipe insulation on piping extending out of dirt crawl space.
3. Concealed roofing materials.
4. Gaskets inside furnace, and concealed furnace refractory insulation.

2.07 LEAD SURVEY RESULTS, BUILDING 2

Lead field survey data sheets and laboratory reports are included as Appendix B. The drawing in Appendix C shows locations where lead samples were taken. Refer to the field survey data sheets for additional information on materials sampled, and detected quantities of lead. The following table summarizes the lead survey results for Building 2.

| Sample No. | Description/Location | Results, % Lead |
|------------|--|-----------------|
| GH 997-L13 | Greenish paint on gypsum/Center of N wall | 0.0373 % |
| GH 997-L14 | Greenish paint on wood window trim/NE window frame | 0.206 % |
| GH 997-L15 | Gray & blue floor paint on tar linoleum/Furnace room floor | 0.670 % |
| GH 997-L16 | White ceiling paint/@ paper joint tape center | 0.0469 % |

Interior finish materials typically contained detectable quantities of lead. The exterior paints were not sampled, but are assumed to contain a relatively high percentage of lead, similar to the exterior paint on the other two buildings.

Paints in Building 2 were typically in good condition, with peeling paint noted at holes in the ceiling of the main room, and in the furnace room where it was damaged by water leaks at the furnace flue.

The following materials were assumed to contain lead, and were not sampled:

1. Solder joints of copper piping.
2. Lead flashing at roof penetrations.
3. Leaded joints of cast iron bell and spigot piping.

2.08 CHEMICAL HAZARDS SURVEY RESULTS, BUILDING 2

All types of fluorescent light fixtures were inspected at random for the presence of Poly chlorinated biphenyl (PCB) containing ballasts. None of the light ballasts in Building 2 had "NO PCBs" printed on their labels. Electrical switches and thermostats commonly contain mercury, as do fluorescent light fixture tubes.

There was a total of 5, four tube fluorescent light fixtures and 2, two tube fluorescent light fixtures in Building 2.

2.09 DESCRIPTION OF BUILDING 3, WIRELESS BUILDING

The central portion of the Wireless Building was constructed in 1917. The building description in "Patterns of the Past, An Inventory of Anchorage's Historic Resources" incorrectly infers that the cupola was "re-centered", when in fact equal additions were constructed to the north and south of the original building. The 1983 nomination to the NRHP listed the south addition as being built prior to 1948, with the north addition being added in 1964. Those dates are partly confirmed by the aerial photographs from 1950 and 1964 and the presence of the original roofing and structure underneath the roofing for the north and south additions.

The original portion of the building had a concrete exterior foundation, apparently with central pier footings. The dirt floor of this crawl space was partly excavated to allow the installation of the perimeter heating piping. The flooring along the west wall has subsided at least 8 inches along the entire 28 foot length of the original building. The slumping of the west wall of the original structure is also evident at the eave line.

The north addition had a shallow foundation with an access hole from the exterior on the north side. The flooring structure had failed at the north east corner of the building due to dry-rot damage.

Building 3 had a mixture of finishes on walls and ceilings, consisting mainly of plywood and 1x3, 1x4, or 1x2 dimensional wood in the original portion, mixed with cellulose board, and small areas of gypsum wall board. The north addition had cellulose board walls and ceilings which had asbestos in the joint compound. The south addition had gypsum wall board walls and ceilings which had asbestos in the joint compound.

The flooring materials were covered with plywood or a hardboard in most areas of the main floor. The flooring materials were inspected at random, by prying up portions of the wood or hardboard covering. None of the flooring materials which were sampled in Building 3 contained asbestos, but areas of concealed flooring that were not sampled may exist. The original portion of the building had a jute backed linoleum flooring with a tar paper and horse hair underlayment. The north addition had a jute-backed linoleum flooring that was typically exposed. The south addition had a jute backed linoleum flooring with a gray paper underlayment that was concealed by both plywood and hardboard.

The south addition had a full height concrete basement divided into 3 rooms. An unusual 15 inch wide concrete wall in the south west corner of this basement extends through the first floor joist space to the wood flooring above, apparently as support for equipment that has since been removed. Although damp, the air circulation in the basement has prevented major deterioration of the wooden first floor structure of the south addition.

Building 3 had been heated by a furnace located in the southeast corner of the building. Uninsulated ducts were located in the rooms. The air returned to the furnace through a grill at the base of the furnace. The oil fired furnace had been converted to natural gas in approximately 1980. The basement housed an oil fired boiler which was installed in 1968. It is not known if this boiler replaced an earlier one, but the boiler was apparently abandoned when the furnace was installed in 1978.

There was asbestos-containing pipe insulation on the cold water pipe in the basement extending vertically out of the disconnected service entrance box. Building 3 had been served with hot water from an electric water heater.

The heating piping from the boiler was insulated in the basement area with an asbestos-containing "aircell" cardboard like insulation. Portions of the heating piping were uninsulated, and other portions had an asbestos-free cellular glass insulation that was adhered together with a white compound that was assumed to contain asbestos. This white compound was only noted at the center of the crawl space where it was inaccessible for sampling.

2.10 ASBESTOS SURVEY RESULTS, BUILDING 3

Asbestos field survey data sheets and laboratory reports are included as Appendix A. The drawing in Appendix C shows locations where the asbestos samples were taken. Refer to the field survey data sheets for additional sample information. The following table summarizes the asbestos survey results for Building 3.

| Sample No. | Description/Location | Results |
|-------------------|---|----------------|
| GH 997-64 | Cellulose board on ceiling/NW room @ ceiling | None Detected |
| GH 997-65 | Gray linoleum with jute backing-black mastic/NE room @ radiator holes | None Detected |

| Sample No. | Description/Location | Results |
|------------|--|--------------------------------|
| GH 997-66 | Cellulose board on wall with joint compound/NE room, NE corner. Composite sample reported as <1% Chrysotile. Joint compound contained 2% Chrysotile. | <1% Chrysotile (2% Chrysotile) |
| GH 997-67 | Gypsum board with joint compound/SE room. Composite sample reported as <1% Chrysotile. Joint compound contained 2% Chrysotile. | <1% Chrysotile (2% Chrysotile) |
| GH 997-68 | Gray linoleum with jute backing-black mastic/NW room @ radiator holes | None Detected |
| GH 997-69 | Heavier gray building paper/Former wall location, center W room | None Detected |
| GH 997-70 | Shiny black building paper/Former wall location, center W room | None Detected |
| GH 997-71 | Thin building paper/Beneath 1"x3" T & G flooring NW room @ radiator hole | None Detected |
| GH 997-72 | Reddish jute backed linoleum with black tarpaper/Center West room at door to NW | None Detected |
| GH 997-73 | Black tar paper & assumed horse hair underlayment/Center West room @ S column | None Detected |
| GH 997-74 | Brown jute backed linoleum with white paper/Center west room @ S. column | None Detected |
| GH 997-75 | Building paper with assumed horse hair/Exterior wall of Center west room | None Detected |
| GH 997-76 | Reddish brown tarry linoleum/Former toilet, center west room | None Detected |
| GH 997-77 | Shiny black building paper/Former toilet wall, center west room | None Detected |
| GH 997-78 | Paper ply -1/4" (paper/wd/paper) patch @ former toilet wall, center west room | None Detected |
| GH 997-79 | Hardboard floor/W side of S room, nailed down | None Detected |
| GH 997-80 | Yellowish jute backed linoleum with gray underlay/W side of S room | None Detected |
| GH 997-81 | Hardboard floor/S room by chimney, nailed down | None Detected |
| GH 997-82 | Brown jute backed linoleum with gray underlay/S room by chimney | None Detected |
| GH 997-83 | Gasket @ view hole/Rheem Model 4225-130EB, serial no. AD113 F3576 8124 | None Detected |
| GH 997-84 | Brown jute backed linoleum with gray underlay/@ door to toilet | None Detected |
| GH 997-85 | Celotex board, no joint compound/E wall of W room | None Detected |
| GH 997-86 | Celotex board, no joint compound/NW wall of S room | None Detected |
| GH 997-87 | Gypsum board, no joint compound/NW wall of S room | None Detected |

| Sample No. | Description/Location | Results |
|------------|--|-----------------------------------|
| GH 997-88 | Tarpaper roofing with grit surface of original building /S side near cut through to S addition | 25% Chrysotile |
| GH 997-89 | Fiberglass with tarry vapor barrier/Attic of S addition | None Detected |
| GH 997-90 | Fiberglass with tarry vapor barrier/Attic of original bldg. | None Detected |
| GH 997-91 | Tarpaper roofing with grit surfacing of original bldg./N side near cut through to N addition | 20% Chrysotile |
| GH 997-92 | Fiberglass with tarry vapor barrier/Attic of N addition | None Detected |
| GH 997-93 | Cloth & rubber wire insul. /Attic near hatch | None Detected |
| GH 997-94 | Hardboard floor/Center NE room @ S door under plywood | None Detected |
| GH 997-95 | Hardboard floor with black mastic/Center NE room @ S door-under #94 | None Detected |
| GH 997-96 | Black tar paper under hardboard/Center NE room @ N door | None Detected |
| GH 997-97 | White window putty/NE windows, N. addition | None Detected |
| GH 997-98 | White window putty/S window, W side original bldg. | None Detected |
| GH 997-99 | Tar paper on exterior wall/Hole @ corner of old to S addition | None Detected |
| GH 997-100 | Cellulose board @ exterior wall/Hole @ corner of old building to S addition | None Detected |
| GH 997-101 | Cement fiberboard/By basement boiler | 40% Chrysotile <1% Crocidolite |
| GH 997-102 | "Aircell" pipe insul. /@ wood wall penet., center bsmt | 90% Chrysotile |
| GH 997-103 | "Mag" pipe insul. on fitting/@ capped tee, bsmt | 40% Chrysotile 20% Crocidolite |
| GH 997-Q5 | Quality control sample to GH 997-72, Reddish jute backed linoleum with black tarpaper/C. West room at door to NW | None Detected |
| GH 997-Q6 | Quality control sample to GH 997-80, Yellowish jute backed linoleum with gray underlay/W side of S room | None Detected |

The following materials were found to contain asbestos:

| <u>Material</u> | <u>Asbestos content</u> |
|---|------------------------------------|
| 1. Joint compound of cellulose board in north addition | 2% Chrysotile |
| 2. Joint compound of gypsum wall board at south addition | 2% Chrysotile |
| 3. Grit surfaced roofing of original building | 25% Chrysotile |
| 4. Cement asbestos board on wall & ceiling adjacent to boiler in basement | 40 % Chrysotile <1% Crocidolite |
| 5. "Aircell" pipe insulation on runs of heating pipe and domestic water piping in basement | 90% Chrysotile |
| 6. "Mag" hard and chalky insulation on fittings of heating and domestic water piping in basement. | 40% Chrysotile 20% Crocidolite |

The following materials were assumed to contain asbestos.

1. Cement asbestos board lining of cabinet on east wall of south room.
2. Cement asbestos board lining of chimney stack through the roof.
3. Window caulking.
4. Sealants on metal roofing.
5. Concealed roofing materials.
6. Gaskets inside furnace and boiler, and concealed furnace and boiler refractory insulation.
7. Adhesive for cellular glass pipe insulation in crawl space.

2.11 LEAD SURVEY RESULTS, BUILDING 3

Lead field survey data sheets and laboratory reports are included as Appendix B. The drawing in Appendix C shows locations where lead samples were taken. Refer to the field survey data sheets for additional information on materials sampled, and detected quantities of lead. The following table summarizes the lead survey results for Building 3.

| Sample No. | Description/Location | Results, % Lead |
|-------------------|--|------------------------|
| GH 997-L17 | Off green paint on plywood/E central room, S wall | 2.01 % |
| GH 997-L18 | Off white ceiling paint on plywood/E central room, center | 0.0714 % |
| GH 997-L19 | Off green paint on cellulose board/NE room, E wall | 1.36 % |
| GH 997-L20 | Off green paint on wood/NE room, @ window trim | 3.38 % |
| GH 997-L21 | White paint on cellulose ceiling/Center of NW room | 0.0999 % |
| GH 997-L22 | Off green on wood/Center W room on base trim | 0.523 % |
| GH 997-L23 | Off green on wood/Former exterior trim 1'x2' T+G | 0.651 % |
| GH 997-L24 | Black & light green on wood/Center W room @ base trim | 0.464 % |
| GH 997-L25 | Off green & white on cellulose board/Center W room | 0.495 % |
| GH 997-L26 | Cream & brown paint on wood/3/4" vertical groove-former NW corner of center W room | 0.287 % |
| GH 997-L27 | White exterior paint on wood/Near S window, W side-original building | 9.56 % |
| GH 997-L28 | Green exterior trim paint on wood/Sill of N window, W side, original building | 13.9 % |
| GH 997-L29 | White & green flaky paint/Concrete N wall, bsmt | 4.29 % |
| GH 997-L30 | Gray paint on wood/Ceiling of W basement | 3.68 % |
| GH 997-L31 | White paint on wood/Center wall of basement | 5.16 % |

Interior finish materials typically contained detectable quantities of lead, with the highest concentrations found in the basement and the exterior paints.

The white and green exterior paints had high concentrations of lead.

Paints in Building 3 were typically in poor condition, with peeling paint noted throughout the building, apparently due to high moisture content in the building. The basement area in particular had peeling paint on all of the concrete walls.

The following materials were assumed to contain lead, and were not sampled:

1. Solder joints of copper piping.
2. Leaded joints of cast iron bell and spigot piping.
3. Lead flashing at roof penetrations.
4. Lead conduit for telephone and signal wiring.

2.12 CHEMICAL HAZARDS SURVEY RESULTS, BUILDING 3

All types of fluorescent light fixtures were inspected at random for the presence of Poly chlorinated biphenyl (PCB) containing ballasts. None of the light ballasts in Building 3 had "NO PCBs" printed on their labels. Electrical switches and thermostats commonly contain mercury, as do fluorescent light fixture tubes.

There was a total of 5, four tube fluorescent light fixtures and 12, two tube fluorescent light fixtures in Building 3.

PART 3, CONCLUSIONS AND RECOMMENDATIONS

3.01 ASBESTOS

Asbestos-containing materials are not required to be removed by any state or federal regulations. However their disturbance, handling and disposal is highly regulated. Owners and managers of buildings which have not been declared to be asbestos free are required to conduct a good faith survey for asbestos prior to any renovation or demolition. Owners and managers are further required to notify building occupants, maintenance and custodial workers of the presence of asbestos-containing materials so that they will not disturb the materials without proper training and protective equipment.

Because the buildings which comprise the Government Hill Wireless Station are not occupied, the requirements may be less stringent. However, access to areas of the buildings which contain damaged and friable asbestos should be restricted to those with proper training in recognizing asbestos and all visitors should avoid disturbance of any asbestos-containing materials.

State and federal laws regulate construction worker exposure to asbestos. The regulations also regulate the disposal of these materials. Worker exposure, controlled by rigidly established permissible exposure limits (PEL), is limited by requiring that engineering controls, personal protective equipment, and worker exposure monitoring be instituted any time asbestos is disturbed during building renovation work. The disposal of these materials is similarly restricted by regulations which license the disposal sites receiving them.

The Environmental Protection Agencies classifies two categories of ACM: friable and nonfriable. Friable materials are materials that can be crumbled to a powder by hand pressure. Nonfriable materials are materials such as floor tiles, roofing felts and coatings, gaskets and mastics that normally bind the asbestos fibers in some sort of matrix that prevents fiber release unless sanding, grinding, sawing or other similar types of abrading occurs.

Only non-friable ACM was found in the main ground floor areas of the buildings, but friable ACM was found in the basement of Building 3 and the crawl spaces of Buildings 1 and 2, as well as in the attic of Building 2.

The gypsum wall board of portions of each of the buildings had asbestos in the joint compound. The joint compound applied to the cellulose wall board of the north addition of Building 3 also contained asbestos. The wall board system as a whole contains less than 1 % asbestos when the wall board and joint compound was analyzed as a composite sample. OSHA requires the disturbance or removal of gypsum wall board or cellulose wall board with asbestos-containing joint compound to be conducted as Class II asbestos work.

The wall board with asbestos-containing joint compound can release asbestos fibers during dry demolition. The debris from the gypsum board can be disposed of under EPA criteria as ordinary construction waste, if allowed by the receiving landfill.

3.02 LEAD

Lead-containing materials are not required to be removed by any state or federal regulations and are thus similar to asbestos-containing materials. However their disturbance, handling and disposal is regulated. Owners and managers are required to notify building occupants, maintenance and custodial workers of the presence of lead-containing materials so that they will not disturb the materials without proper training and protective equipment.

Because the buildings which comprise the Government Hill Wireless Station are not occupied, the requirements may be less stringent. However, visitors should avoid disturbance of any lead-containing materials, and should wash any skin that has contacted lead-containing materials prior to eating or applying cosmetics.

State and federal laws regulate all construction work where employees may be exposed to lead. Even at low concentrations of lead, worker exposure to lead remains possible during demolition or disturbance of lead-containing materials. The contractor is required to monitor his/her workers to determine if they will be exposed to lead at or above the action level established in the regulation. Until this "initial determination" establishes that workers are not exposed above the permissible exposure limit, the contractor is required to provide workers with adequate personnel protection. Continued air and medical monitoring may be required if exposure is above the action level.

One hazard which lead paint potentially creates occurs when the lead becomes airborne and can then be inhaled. When the painted materials are cut, welded or otherwise disturbed the lead can

become airborne. An additional hazard is the ingestion of lead paint chips that are not airborne. Lead particles may be released when building demolition or renovation activities disturb contaminated materials; consequently, the regulations have established work practices, exposure monitoring, and worker training requirements.

Lead paint stripping operations may create additional hazards due to the toxicity of the stripping chemicals. The application of heat guns for stripping operations may create an even greater hazard by promoting airborne lead fumes. Lead paint stripping may be required locally at cutting and welding operations on existing miscellaneous steel components.

Renovation or demolition projects would produce wastes with lead-containing paints. In order to classify the lead wastes as hazardous or non-hazardous for disposal purposes, TCLP (Toxicity Characteristic Leaching Procedure) tests are required by the EPA. The TCLP test determines the leachability of lead from the paint while adhered to the substrate. Currently, the maximum allowable leachate of lead in order to be classified as a non-hazardous waste is 5 milligrams of lead per liter of leachate (mg/l). Anything above this 5 mg/l level is classified as hazardous waste and must be disposed of at an approved permitted TSD (Transportation, Storage, Disposal) facility. There are no permitted hazardous waste disposal sites in Alaska. TCLP tests will need to be performed on representative samples of any renovation project wastes to determine the lead waste disposal requirements.

3.03 CHEMICAL HAZARDS

Polychlorinated Biphenyl containing and mercury-containing materials were identified in fluorescent light ballasts in each of the buildings. Mercury containing materials were identified in fluorescent light fixture tubes, electrical thermostats and switches in each of the buildings.

These materials typically present a hazard only when they are disturbed and contact the skin. Disposal of these materials are regulated by the EPA because improper disposal will contaminate the environment. PCB and mercury containing materials are required to be properly handled and packaged for disposal, but may remain in place until they are no longer in service.

Mercury containing wastes from fluorescent light tubes and switches will typically fail the TCLP test. Currently, the maximum allowable leachate of mercury in order to be classified as a non-hazardous waste is 0.2 milligrams of mercury per liter of leachate (mg/l). Anything above this 0.2 mg/l level is classified as hazardous waste and must be disposed of at an approved permitted TSD (Transportation, Storage, Disposal) facility.

PART 4, REGULATIONS

4.01 ASBESTOS

The Federal Occupational Safety and Health Administration (OSHA) and the State of Alaska Department of Labor (AKDOL) have adopted regulations applying to workplace activities involving asbestos. 29 CFR 1926.1101 sets permissible exposure limits; establishes contamination controls, work practices, and medical surveillance; and requires worker certification and protective equipment. AKDOL requires asbestos workers to be certified in accordance with Title 18, Chapters 61.600-790 of the Alaska Administration Code.

The Environmental Protection Agency (EPA) regulations (40 CFR 61) under the National Emission Standards for Hazardous Air Pollutants (NESHAP) established procedures for handling ACM during asbestos removal and waste disposal. These regulations require an owner (or the owner's contractor) to notify the EPA of asbestos removal operations and to establish responsibility for the removal, transportation, and disposal of asbestos.

The disposal of asbestos waste is regulated by the EPA, the State of Alaska Department of Environmental Conservation, and the disposal site operator. Wastes being transported to the disposal site must be sealed in double walled containers (double bagged) prior to disposal and must be accompanied by disposal permits and waste manifests.

4.02 LEAD

OSHA and AKDOL have adopted regulations applying to workplace activities involving lead. 29 CFR 1926.62 sets permissible exposure limits; establishes contamination controls, work practices, and medical surveillance; and requires worker training and protective equipment.

The EPA regulations, (40 CFR 260-272) under the Resource Conservation and Recovery Act (RCRA) established regulations for the handling, storage and disposal of hazardous materials. TCLP tests are required to be conducted in accordance with method 1311 of, Appendix II.

The Department of Transportation (DOT) regulations, (49 CFR 171-180) established regulations for the transportation of hazardous materials. All hazardous wastes must be accompanied by disposal permits and waste manifests.

4.03 CHEMICAL HAZARDS

The EPA regulations, (40 CFR 761) under the Toxic Substance Control Act (TSCA) established regulations for the handling, storage and disposal of Polychlorinated Biphenyl containing materials. The EPA regulations, (40 CFR 261) under the Resource Conservation and Recovery Act (RCRA) established regulations for the handling, storage and disposal of mercury-containing materials.

The Department of Transportation (DOT) regulations, (49 CFR 171-180) established regulations for the transportation of hazardous materials, including PCBs and mercury-containing materials. All hazardous wastes must be accompanied by disposal permits and waste manifests.

APPENDIX A

Asbestos Field Data Sheets and Laboratory Reports



EHS ALASKA
INCORPORATED

Environmental Health Sciences-Alaska, Inc.
10928 Eagle River Road, Suite 202, Eagle River, AK 99577-8052
(907) 694-1383 • (907) 694-1382 fax

CHAIN OF CUSTODY RECORD/FIELD SURVEY DATA

Page 1 of 9

FIELD COLLECTION DATE: 9-19-97 JOB #: 3968-01-02 MATERIAL TYPE: (Circle) ASBESTOS LEAD TOTAL QUANTITIES: 103

PROJECT NAME: Gov. Hill Telegraph Bldg 2 BULK ANALYSIS REQUESTED: (Circle) PLM/ PLM DUST / TEM BULK / LEAD TCLP / LEAD PPM

FACILITY: Gov. Hill Wireless Sta. DISPOSAL: Routine TURNAROUND: 3 days

SPECIAL INSTRUCTIONS:

COLLECTED BY (signature) Robert French
PRINTED NAME Robert French
CERT# 1564 88IMP-008
SHIPPER (signature) Robert French
SHIPMENT (signature) Robert French
DATE/TIME 9:22 10:00 a.m.

San Leandro
R J Lee Gyp.
SELECTED LABORATORY
SAMPLES ACCEPTED BY
DATE/TIME 9:23 9:15 AM
ANALYST'S SIGNATURE
DATE 9-23-97

COMMENTS:
OK if Results take more than 3 days due to quantity
Please fax results in groups of ~ 30

| SAMPLE ID | SAMPLE DESCRIPTION, (COLOR, MATERIAL TYPE, LAYERS, FRIABILITY) | LOCATION/COMMENTS (INCLUDING PHOTO/XREF) | RESULTS |
|------------------|--|---|-----------------------|
| 1. GH 997 - 1 | Gyp, Mud + Tape MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | South office Bldg 1 SE Corner Ph 1054 2% Chrys. in Joint Comp. | < 1% - C Composite |
| 2. GH 997 - 2 | Red Brick Pattern 'self-stic' 12"x12" tile MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | South office Bldg 1 at Door Ph 1055 | 3% Chrysotile |
| 3. GH 997 - 3 | Gyp, Mud + Tape MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Main South Room Bldg 1 at Furnace Rm 2% Chrysotile in Joint Comp. | < 1% - C Composite |
| 4. GH 997 - 4 | Cement Fiber Board MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Furnace Rm Bldg 1 South wall | 40% Chrysotile |
| 5. GH 997 - 5 | Gyp, Mud + Tape MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | North Rm Bldg 1 at Furnace Rm | None Detected |
| 6. GH 997 - 6 | Gyp, Mud + Tape MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | North Rm Bldg 1 NW corner | None Detected |
| 7. GH 997 - 7 | Red Brick Pattern 'self-stic' 12"x12" F.T. MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | South Office Bldg 1 at West wall | 4% Chrysotile |
| 8. GH 997 - 8 | Bldg Paper MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Exterior - under siding SE corner Bldg 1 | None Detected |

RETURN A SIGNED COPY OF THIS FORM WITH THE FINAL REPORT TO EHS-ALASKA

EHS-9/95



EHS ALASKA
INCORPORATED

Environmental Health Sciences-Alaska, Inc.
10928 Eagle River Road, Suite 202, Eagle River, AK 99577-8052
(907) 694-1383 • (907) 694-1382 fax

FIELD SURVEY DATA (continued)

Page 2 of 9

| PROJECT NAME: <u>Gov. Hill Telegraph EA2</u> | | FACILITY: <u>Gov. Hill Wireless Sta.</u> | |
|--|--|--|-----------------------------|
| JOB NUMBER: <u>3968-01-02</u> | | DATE: <u>9-19-97</u> | COLLECTED BY: <u>French</u> |
| SAMPLE ID | SAMPLE DESCRIPTION, (COLOR, MATERIAL TYPE, LAYERS, FRIABILITY) | LOCATION/COMMENTS (INCLUDING PHOTO/REF) | RESULTS |
| ✓ GH997-9 | White roxy gasket at Furnace MATERIAL CONDITION: <u>GOOD FAIR POOR</u> DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | At Burner plate Bldg 1 to Furnace Body Ph 1113 | 80% Chrys. 5% Amosite |
| ✓ GH997-10 | White waxy wire insulation MATERIAL CONDITION: <u>GOOD FAIR POOR</u> DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | At Incand. Light Bldg 1 on Fixture Side Ph 1131 | 50% Chrysotile |
| ✓ GH997-11 | Rubbery wire insul MATERIAL CONDITION: <u>GOOD FAIR POOR</u> DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | At Incand. Light Bldg 1 on House side Ph 1131 | None Detected |
| ✓ GH997-12 | Red woven wire insul MATERIAL CONDITION: <u>GOOD FAIR POOR</u> DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | At Fluors. Light Bldg 1 @ Fixture side Ph 1136 | None Detected |
| ✓ GH997-13 | Gyp, Mud + Tape MATERIAL CONDITION: <u>GOOD FAIR POOR</u> DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | behind door in Bldg 1 Toilet, West Wing 2% Chrysotile in Joint | <1% Chrys. Composite |
| ✓ GH997-14 | Lt brown - 1/4" chips SV MATERIAL CONDITION: <u>GOOD FAIR POOR</u> DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | At Floor Hatch Bldg 1 in Toilet, West Wing Ph 1307 2% Chrys. in Mastec | 35% Chrysotile |
| ✓ GH997-15 | Boorn Core Box Material MATERIAL CONDITION: <u>GOOD FAIR POOR</u> DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Behind door in Toilet, West Wing Bldg 1 | None Detected |
| ✓ GH997-16 | Tar Paper underlayment MATERIAL CONDITION: <u>GOOD FAIR POOR</u> DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Between Particle Bed + part T+6 + lap bds T+6 lap Ph 1307 Bldg 1 | None Detected |
| ✓ GH997-17 | White Cardboard Insul MATERIAL CONDITION: <u>GOOD FAIR POOR</u> DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | in crawl space Ph 1317 Bldg 1 | 85% Chrysotile |
| ✓ GH997-18 | Tar Paper underlayment MATERIAL CONDITION: <u>GOOD FAIR POOR</u> DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | under toilet @ Dry Rot Ph 1319 Bldg 1 | None Detected |
| ✓ GH997-19 | White Cardboard Insul MATERIAL CONDITION: <u>GOOD FAIR POOR</u> DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | in crawl space off of pipe Bldg 1 | 95% Chrysotile |
| ✓ GH997-20 | Gray, late backed limestone MATERIAL CONDITION: <u>GOOD FAIR POOR</u> DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | on wall of toilet Ph 1328 Bldg 1 | None Detected |



EHS ALASKA
INCORPORATED

Environmental Health Sciences-Alaska, Inc.
10928 Eagle River Road, Suite 202, Eagle River, AK 99577-8052
(907) 694-1383 • (907) 694-1382 fax

FIELD SURVEY DATA (continued)

Page 3 of 9

PROJECT NAME: Gov Hill Telegraph EA2

FACILITY: Gov Hill Wireless Sta.

JOB NUMBER: 3968-01-02

DATE: 9-19-97

COLLECTED BY: French

| SAMPLE ID | SAMPLE DESCRIPTION, (COLOR, MATERIAL TYPE, LAYERS, FRIABILITY) | LOCATION/COMMENTS (INCLUDING PHOTO/XREF) | RESULTS |
|------------|--|--|-------------------|
| ✓ GH997-21 | Cove Base + Mastu Brown creamy MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | West Wing Kitchen Ph 1342 Bldg 1 | None Detected |
| ✓ GH997-22 | Lt Brown Chip - Sh. Vn l. MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | At hole in Floor between rooms Ph 1344 Bldg 1 | 35% Chrysotile |
| ✓ GH997-23 | Cove Base + creamy brown waste MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Middle Room in West Wing Bldg 1 | None Detected |
| ✓ GH997-24 | Insul @ Incand. light + Mastu MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Kitchen, west wing Bldg 1 | None Detected |
| ✓ GH997-25 | Pink Fib Ch insul MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | NW corner, kitchen Bldg 1 | None Detected |
| ✓ GH997-26 | Blown in Mixed Insul MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | NW corner, kitchen Bldg 1 | None Detected |
| ✓ GH997-27 | Brown crepe paper ceiling insul MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | S side above kitchen Bldg 1 | None Detected |
| ✓ GH997-28 | Blown in Mixed Insul MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Middle above kitchen Bldg 1 | None Detected |
| ✓ GH997-29 | Cable end Tan Paper MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | West end of Attic Bldg 1 | None Detected |
| ✓ GH997-30 | Roof Tan Paper MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | above Hatch in Kitchen Bldg 1 | None Detected |
| ✓ GH997-31 | Brown crepe paper dust insul MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | above Hatch in Kitchen Bldg 1 | None Detected |
| ✓ GH997-32 | Red + White Floor tile w/ Black Mastu MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | in crawl space below kitchen Bldg 1 N.D. in Mastic | 5% Chrysotile |



EHS ALASKA
INCORPORATED

Environmental Health Sciences-Alaska, Inc.
10928 Eagle River Road, Suite 202, Eagle River, AK 99577-8052
(907) 694-1383 • (907) 694-1382 fax

FIELD SURVEY DATA (continued)

Page 4 of 9

PROJECT NAME: Gou Hill Telegraph EA2

FACILITY: Gou Hill Wireless Sta.

JOB NUMBER: 3968-01-02

DATE: 9-19-97

COLLECTED BY: French

| SAMPLE ID | SAMPLE DESCRIPTION, (COLOR, MATERIAL TYPE, LAYERS, FRIABILITY) | LOCATION/COMMENTS (INCLUDING PHOTO/REF) | RESULTS |
|--------------|--|--|---|
| ✓ GH997 - 33 | Roof tan Paper MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | North wing above Hatches Bldg 1 | None Detected |
| ✓ GH997 - 34 | Blown in Multi colored ceiling Insul MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | North wing south of Hatch Bldg 1 | None Detected |
| ✓ GH997 - 35 | Blown in Multi-colored ceiling Insul MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | North wing North of Hatches Bldg 1 | None Detected |
| ✓ GH997 - 36 | Celotex Board ceiling MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Above cly to South wing Bldg 1 | None Detected |
| ✓ GH997 - 37 | Celotex Board ceiling MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Above cly to South wing Bldg 1 | None Detected |
| ✓ GH997 - 38 | Window caulking MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Furnace Room Window Ph 1513 Bldg 1 | <1% Chrysotile |
| ✓ GH997 - 39 | Black + gray roof patching MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | @ 3" pipe from above kitchen Bldg 1 | 10% Chrysotile |
| ✓ GH997 - 40 | Black + silver roofing - MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Under Metal roofing Bldg 1 | 1% chrys. Composite 10% C in Silver layer |
| ✓ GH997 - 41 | Black + gray roof patching MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | @ Elec Drop to Bldg 1 | 15% Chrysotile |
| ✓ GH997 - 42 | DK Brown 9x9 Floor tile w/ Black Mortar MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | NW corner of Bldg 2 N.D. in Mortar | 3% Chrysotile |
| ✓ GH997 - 43 | Gyp Mud + Tape MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Center N. wall Ph 1555 Bldg 2 | <1% Composite 3% C in Joint |
| ✓ GH997 - 44 | DK Brown 9x9 Floor MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Center @ Hump Ph 1554 Bldg 2 | 3% Chrysotile |



EHS ALASKA
INCORPORATED

Environmental Health Sciences-Alaska, Inc.

10928 Eagle River Road, Suite 202, Eagle River, AK 99577-8052

(907) 694-1383 • (907) 694-1382 fax

FIELD SURVEY DATA (continued)

Page 5 of 9

PROJECT NAME: Gov Hill Telegraph EA2


FACILITY: Gov Hill Wireless Sta

JOB NUMBER: 3968-01-02

DATE: 9-19-97

COLLECTED BY: French

| SAMPLE ID | SAMPLE DESCRIPTION, (COLOR, MATERIAL TYPE, LAYERS, FRIABILITY) | LOCATION/COMMENTS (INCLUDING PHOTO/REF) | RESULTS |
|------------|--|--|--|
| ✓ GH997-45 | Gyp Mud + Tape MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | outside Corner of Furnace Room Bldg 2 | <1% Chrys. Composite 3% in Joint C. |
| ✓ GH997-46 | Cement Filler Bd on Wall MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Furnace Rm wall PH 1603 Bldg 2 | 40% Chrysotile |
| ✓ GH997-47 | Window Caulking MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | North window PH 1606 Bldg 2 | 1% Chrysotile |
| ✓ GH997-48 | Cement Filler Bd on Floor MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Under Furnace PH 1605 Bldg 2 | 45% Chrysotile |
| ✓ GH997-49 | Rope Gasket on RA Side of Furnace MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Inside Furnace PH 1608 Bldg 2 | 90% Chrysotile |
| ✓ GH997-50 | Gyp Mud + Tape MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | In Toilet PH 1648 Bldg 2 | <1% Chrys. Composite 3% C. in Joint. |
| ✓ GH997-51 | Soft Gasket at Furnace Clean-out MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Rm side of Furnace PH 1650 Bldg 2 | 80% Chrysotile |
| ✓ GH997-52 | Grit Surfaced tar paper Floor underlay MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | at Hatch west side Very Wet + soft Bldg 2 | None Detected |
| ✓ GH997-53 | Gray - redish tar linedum MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | at Hatch at Hatch Bldg 2 | None Detected |
| ✓ GH997-54 | Grit Surfaced tar paper Floor underlay MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | At Hatch, East side Bldg 2 | None Detected |
| ✓ GH997-55 | Gray - redish tar linedum MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | NOB Furnace, Bldg 2 | None Detected |
| ✓ GH997-56 | Dark Brown 9x9 Floor tile w/lt brown mortar MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | SE area Bldg 2 | 3% Chrysotile |



EHS ALASKA
INCORPORATED

Environmental Health Sciences-Alaska, Inc.

10928 Eagle River Road, Suite 202, Eagle River, AK 99577-8052

(907) 694-1383 • (907) 694-1382 fax

FIELD SURVEY DATA (continued)

Page 6 of 9

PROJECT NAME: Gov Hill Telegraph EA-2

FACILITY: Gov. Hill Wireless Sta

JOB NUMBER: 3968-01-02

DATE: 9-19-97

COLLECTED BY: French

| SAMPLE ID | SAMPLE DESCRIPTION, (COLOR, MATERIAL TYPE, LAYERS, FRIABILITY) | LOCATION/COMMENTS (INCLUDING PHOTO/REF) | RESULTS |
|------------|--|---|--------------------|
| ✓ GH997-57 | Gray Wool cly Insul MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | South side of Attic Bldg 2 | None Detected |
| ✓ GH997-58 | Brit Surface roofing w/ silver coating MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | South middle of Attic Bldg 2 10% in Silver layer | <1% C Composite |
| ✓ GH997-59 | Gray Wool Cg Insul MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Middle of Attic Ph 10 Bldg 2 | None Detected |
| ✓ GH997-60 | Gray Wool cly Insul MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | North side of Attic Bldg 2 | None Detected |
| ✓ GH997-61 | Tar Paper @ Siding MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | North side Cable at Hatch Bldg 2 | None Detected |
| ✓ GH997-62 | White thin Paper MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | loose in Attic Bldg 2 | 95% Chrysotile |
| ✓ GH997-63 | White thin Paper MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | loose in Attic By Hatch Bldg 2 | 95% Chrysotile |
| ✓ GH997-64 | Cellulose Board on Cg MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | NW Room @ ceiling Bldg 3 | None Detected |
| ✓ GH997-65 | Gray linoleum w/ lute backing - black waste MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | NE Room @ Radiat. Hols Ph 1514 Bldg 3 (Mastic not Found) | None Detected |
| ✓ GH997-66 | Cellulose Bd on wall w/ joint comp. MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | NE Room, NE Corner Ph 1514 Bldg 3 2% C in Joint. | <1% Composite |
| ✓ GH997-67 | Gyp Bd w/ joint comp MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | SE Room Bldg 3 2% C in Joint. | <1% Composite |
| ✓ GH997-68 | Gray linoleum w/ lute backing - black waste MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | NW Room at Radiat. Hols. Ph 1536 Bldg 3 | None Detected |



EHS ALASKA
INCORPORATED

Environmental Health Sciences-Alaska, Inc.
10928 Eagle River Road, Suite 202, Eagle River, AK 99577-8052
(907) 694-1383 • (907) 694-1382 fax

FIELD SURVEY DATA (continued)

Page 7 of 9

PROJECT NAME: Gov. Hill Telegraph EA-2

FACILITY: Gov Hill Wireless Sta.

JOB NUMBER: 3968-01-02

DATE: 9-20-97

COLLECTED BY: French

| SAMPLE ID | SAMPLE DESCRIPTION, (COLOR, MATERIAL TYPE, LAYERS, FRIABILITY) | LOCATION/COMMENTS (INCLUDING PHOTO/REF) | RESULTS |
|------------|--|--|------------------|
| ✓ GH997-69 | Heavier Gray Bldg Paper MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Former wall location, Center West Room Ph 1542 Bldg 3 | None Detected |
| ✓ GH997-70 | Black Bldg Paper MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Former wall location Center West Room Ph 1542 Bldg 3 | None Detected |
| ✓ GH997-71 | Thin Bldg Paper MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Beneath 1x3 Floorj NW Room @ Radistor Mote Bldg 3 | None Detected |
| ✓ GH997-72 | Reddish floor Jute Backed linoleum w/Black tarpaper MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Center West Room at Door to NW Ph 1552 Bldg 3 | None Detected |
| ✓ GH997-73 | Black tar Paper & Horse hair? under laymant MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Center West @ S. column Ph 155 Bldg 3 | None Detected |
| ✓ GH997-74 | Brown Jute Backed linoleum w/ white paper MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Center West room @ S. column Bldg 3 | None Detected |
| ✓ GH997-75 | Bldg Paper w/ Horse Hair? MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Ext. Wall of West C. Room Ph 1610 Bldg 3 | None Detected |
| ✓ GH997-76 | Reddish Brown Tarry linoleum MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Former Toilet, Center West Room Ph 16189 Bldg 3 | None Detected |
| ✓ GH997-77 | Shiny Black Bldg Paper MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Former toilet wall, Center West Rm Ph 1624 Bldg 3 | None Detected |
| ✓ GH997-78 | Paper Ply - 1/4" Paper/wd/paper! MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Patch at Former Toilet wall, Center West Rm Ph 1624 Bldg 3 | None Detected |
| ✓ GH997-79 | Hardboard Flooring MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | West Side of S. Room Ph 16534 Bldg 3 | None Detected |
| ✓ GH997-80 | Yellowish Jute Backed linoleum w/ Gray underlay MATERIAL CONDITION: GOOD FAIR POOR DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | West Side of S. Room Ph 1654 Bldg 3 | None Detected |



EHS ALASKA
INCORPORATED

Environmental Health Sciences-Alaska, Inc.
10928 Eagle River Road, Suite 202, Eagle River, AK 99577-8052
(907) 694-1383 • (907) 694-1382 fax

FIELD SURVEY DATA (continued)

Page **8** of **9**

| PROJECT NAME: Gov. Hill Telegraph EA-2 | | FACILITY: Gov. Hill Wireless Sta | |
|---|---|--|-----------------------------|
| JOB NUMBER: 3968-01-02 | | DATE: 9-20-97 | COLLECTED BY: French |
| SAMPLE ID | SAMPLE DESCRIPTION, (COLOR, MATERIAL TYPE, LAYERS, FRIABILITY) | LOCATION/COMMENTS (INCLUDING PHOTO/REF) | RESULTS |
| ✓ GH997-81 MATL. CONDITION: GOOD FAIR POOR | Hardboard Flooring DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | South Room by Chimney Ph 1708 Bldg 3 | None Detected |
| ✓ GH997-82 MATL. CONDITION: GOOD FAIR POOR | Brown, Inte Backed lined, w/ gray underlay DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | South Room by Chimney Ph 1708 Bldg 3 | None Detected |
| ✓ GH997-83 MATL. CONDITION: GOOD FAIR POOR | Gasket at View hole DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Rheem Mod 4225-130 EB sn AD113 F 3576 8124 Ph 1714 Bldg 3 | None Detected |
| ✓ GH997-84 MATL. CONDITION: GOOD FAIR POOR | Brown, Inte Backed lined, w/ Gray underlay DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | At door to toilet Ph 1728 Bldg 3 | None Detected |
| ✓ GH997-85 MATL. CONDITION: GOOD FAIR POOR | celotex bd, no joint comp DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | East Wall of South Room West Ph 1743 Bldg 3 | None Detected |
| ✓ GH997-86 MATL. CONDITION: GOOD FAIR POOR | celotex bd, no joint comp DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | SE corner of West Rm Ph 1744 Bldg 3 | None Detected |
| ✓ GH997-87 MATL. CONDITION: GOOD FAIR POOR | Gyp Bd - no joint comp DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | NW wall of South Room Bldg 3 | None Detected |
| ✓ GH997-88 MATL. CONDITION: GOOD FAIR POOR | Tarpaper Roofing w/ grit surf. DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | S. Side near cut thru to S. addn, of orig Bldg Bldg 3 | 25% Chrysotile |
| ✓ GH997-89 MATL. CONDITION: GOOD FAIR POOR | FB6 w/ Tarry Vapor Barrier DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Attic of S. Addn. Bldg 3 | None Detected |
| ✓ GH997-90 MATL. CONDITION: GOOD FAIR POOR | FB6 w/ Tarry Vapor Barrier DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Attic of Orig Bldg Ph 1810 Bldg 3 | None Detected |
| ✓ GH997-91 MATL. CONDITION: GOOD FAIR POOR | Tarpaper w/ grit surfacing DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | N. Side of orig bldg near cut thru Bldg 3 | 20% Chrysotile |
| ✓ GH997-92 MATL. CONDITION: GOOD FAIR POOR | Fbs w/ Tarry Vapor barrier DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Attic of N. Addn Bldg 3 | None Detected |



EHS ALASKA
INCORPORATED

Environmental Health Sciences-Alaska, Inc.
10928 Eagle River Road, Suite 202, Eagle River, AK 99577-8052
(907) 694-1383 • (907) 694-1382 fax

FIELD SURVEY DATA (continued)

Page 9 of 9

PROJECT NAME: Gov Hill Telegraph EA-2

FACILITY: Gov Hill Wireless Sta

JOB NUMBER: 3968-01-02

DATE: 9-21

COLLECTED BY: French

| SAMPLE ID | SAMPLE DESCRIPTION, (COLOR, MATERIAL TYPE, LAYERS, FRIABILITY) | LOCATION/COMMENTS (INCLUDING PHOTO/REF) | RESULTS |
|-----------|---|---|--------------------------|
| GH997-93 | Cloth + rubber wire insul | Attic near Hatch Bldg 3 | None Detected |
| GH997-94 | Hard board Floor | Center NE room at S. door under ply Ph 1224 Bldg 3 | None Detected |
| GH997-95 | Hardboard Floor w/ black mastic | Center NE room at south door - under #94 Ph 1224 Bldg 3 | None Detected |
| GH997-96 | Black Tar Paper under hardboard | Center NE Room at North door Ph 1234 Bldg 3 | None Detected |
| GH997-97 | Window Putty, white | NE window N. addn Bldg 3 | None Detected |
| GH997-98 | Window Putty, white | S window, west side Orig. Bldg Bldg 3 | None Detected |
| GH997-99 | Tar Paper on Ext. Wall | #99 Hole at corner of old to S. addn. Bldg 3 | None Detected |
| GH997-100 | Cellulose Board @ Ext. Wall | Hole at corner of old to S. addn Bldg 3 | None Detected |
| GH997-101 | Cement Fiber Bd. | By Bsmr Boilers Ph 13205 Bldg 3 | 40% Chrys 41% Crocid. |
| GH997-102 | Aircell Pipe Insul | At wood wall penetration Ph 1328 Bldg 3 | 90% Chrysotile |
| GH997-103 | "Mag" Pipe Insul on Fitting | At busted up Tee Ph 1334 Bldg 3 | 40% Chrys 20% Crocid. |
| | | | |

RJ Lee Group, Inc.

530 McCormick Street • San Leandro, CA 94577
(510) 567-0480 • FAX (510) 567-0488

September 26, 1997

Mr. Robert A. French
Environmental Health Sciences - Alaska, Inc.
10928 Eagle River Road, Suite 202
Eagle River, AK 99577-8052

RE: PLM Standard Asbestos Analysis Results for Samples as Shown on Test Report
RJLeeGroup, Inc. Job No.: AOC709250
Client P.O./Job Number: 3968-01-02
Client Job Name/Location: 3968-01-02

Dear Mr. French:

Enclosed are the results from the polarized light microscopy (PLM) asbestos analysis of the above referenced sample(s). Sample(s) were analyzed in accordance with guidelines set forth in the EPA Method for the Determination of Asbestos in Bulk Building Materials, U.S. EPA/600/R-93/116 (7/93 Edition).


Test Report lists each sample identification number, gross sample description, sample location, type(s) and concentration of asbestos, type(s) and concentration of nonasbestos fibers, major components and concentration of nonfibrous material (NFM), sample run date, analyst, sample homogeneity, and a layer breakdown if applicable. All concentrations are given in area percents (visual estimation).

RJ Lee Group, Inc. is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) (NVLAP Participant Number 1208-2) for bulk asbestos fiber analysis (PLM), and by the California Department of Health Services, Environmental Laboratory Accreditation Program (CALELAP) for bulk asbestos analysis. Neither the NVLAP Accreditation of this laboratory nor this report may be used to claim product endorsement by NVLAP or any agency of the United States government.

These results are submitted pursuant to RJ Lee Group's current terms and conditions of sale, including the company's standard warranty and limitation of liability provisions and no responsibility or liability is assumed for the manner in which the results are used or interpreted. Unless notified in writing to return the sample(s) covered by this report, RJ Lee Group will store the sample(s) for a period of ninety (90) days before discarding. A shipping and handling fee will be assessed for the return of any sample(s).

If you have any questions on this report or if RJ Lee Group, Inc. can be of further assistance, please do not hesitate to call.

Sincerely,


Scott Stotler
Geologist

SS/dd
Enclosure



Monroeville, PA • San Leandro, CA • Washington, D.C. • Houston, TX
Chopra-Lee, Inc., Grand Island, NY

Test Report-Environmental Health Sciences-AK

Polarized Light Analysis Results

Project AOC709250

-----Asbestos-----Nonasbestos-----

| Sample Number / Sample Appearance | Client Sample Number | Chrysotile | Amosite | Crocidolite | Anthophyllite | Tremolite | Actinolite | Cellulose | Wool | Glass | Fibers | Fibers | Material | Analyst | Run Date |
|---|----------------------|------------|---------|-------------|---------------|-----------|------------|-----------|------|-------|--------|--------|----------|---------|----------|
| 1646736CPL | GH-997-1 | <1 % | - | - | - | - | - | 10 % | - | - | - | - | 90 % | 9/24/97 | SS |
| White gypsum wallboard, white mud, white tape | | | | | | | | | | | | | | | |
| Mud: 2% Chrysotile; Other Layers: None Detected | | | | | | | | | | | | | | | |
| 1646737CPL | GH-997-2 | 3 % | - | - | - | - | - | <1 % | - | - | - | - | 97 % | 9/24/97 | SS |
| Red tile, grey mastic | | | | | | | | | | | | | | | |
| Tile: 3% Chrysotile; Mastic: None Detected | | | | | | | | | | | | | | | |
| 1646738CPL | GH-997-3 | <1 % | - | - | - | - | - | 7 % | - | - | - | - | 93 % | 9/24/97 | SS |
| White gypsum board, white mud, white tape | | | | | | | | | | | | | | | |
| Mud: 2% Chrysotile; Other Layers: None Detected | | | | | | | | | | | | | | | |
| 1646739CPL | GH-997-4 | 40 % | - | - | - | - | - | <1 % | - | - | - | - | 60 % | 9/24/97 | SS |
| Grey cement fiber board | | | | | | | | | | | | | | | |
| 1646740CPL | GH-997-5 | - | - | - | - | - | - | 3 % | 2 % | - | - | - | 95 % | 9/24/97 | SS |
| White gypsum board, white mud, tan tape | | | | | | | | | | | | | | | |
| NFM: Qtz, Carb, Opaq, Gyp, Mica, Misc. Part. | | | | | | | | | | | | | | | |
| Non Homogeneous | | | | | | | | | | | | | | | |
| 1646741CPL | GH-997-6 | - | - | - | - | - | - | 5 % | - | - | - | - | 95 % | 9/24/97 | SS |
| White gypsum board | | | | | | | | | | | | | | | |
| NFM: Qtz, Carb, Opaq, Gyp, Misc. Part. | | | | | | | | | | | | | | | |
| Homogeneous | | | | | | | | | | | | | | | |



Samples received on: Tuesday, September 23, 1997
RJ Lee Group, Inc.
 Bay Area Lab
 530 McCormick Street
 San Leandro, CA 94577
 Page: 1 of 18

Authorized Signature

Date

Scott Stotler, Geologist
 Friday, September 26, 1997
 Phone (510) 567-0480
 Fax (510) 567-0488

Test Report-Environmental Health Sciences-AK

Polarized Light Analysis Results

Project AOC709250

| -----Asbestos-----Nonasbestos----- | | | | | | | | | | | | | | |
|---|----------------------|---|---------|-------------|---------------|-----------|------------|-----------|------|-------|--------|--------|----------|---------|
| Sample Number / | | Mineral Fibrous Synthetic Other NonFibrous Run Date | | | | | | | | | | | | |
| Sample Appearance | Client Sample Number | Chrysotile | Amosite | Crocidolite | Anthophyllite | Tremolite | Actinolite | Cellulose | Wool | Glass | Fibers | Fibers | Material | Analyst |
| 1646742CPL | GH-997-7 | 4 % | - | - | - | - | - | <1 % | - | - | - | - | 96 % | 9/24/97 |
| Red tile, clear mastic | | | | | | | | | | | | | | |
| Layer Content: Tile: 4% Chrysotile; Mastic: None Detected | | | | | | | | | | | | | | |
| 1646743CPL | GH-997-8 | - | - | - | - | - | - | 95 % | - | - | - | - | 5 % | 9/24/97 |
| Brown paper | | | | | | | | | | | | | | |
| NFM: Qtz, Carb, Opaq, Misc. Part. | | | | | | | | | | | | | | |
| 1646744CPL | GH-997-9 | 80 % | 5 % | - | - | - | - | 10 % | - | - | - | - | 5 % | 9/24/97 |
| White/grey gasket at furnace | | | | | | | | | | | | | | |
| NFM: Qtz, Carb, Opaq, Misc. Part. | | | | | | | | | | | | | | |
| 1646745CPL | GH-997-10 | 50 % | - | - | - | - | - | 20 % | - | - | - | - | 30 % | 9/24/97 |
| Tan wire insulation | | | | | | | | | | | | | | |
| NFM: Qtz, Carb, Binder, Opaq, Misc. Part. | | | | | | | | | | | | | | |
| 1646746CPL | GH-997-11 | - | - | - | - | - | - | <1 % | - | - | - | - | 99+ % | 9/24/97 |
| White wire insulation | | | | | | | | | | | | | | |
| NFM: Qtz, Carb, Binder, Opaq, Misc. Part. | | | | | | | | | | | | | | |
| 1646747CPL | GH-997-12 | - | - | - | - | - | - | 20 % | - | - | - | 5 % | 75 % | 9/24/97 |
| Red wire insulation | | | | | | | | | | | | | | |
| NFM: Qtz, Carb, Binder, Opaq, Misc. Part. | | | | | | | | | | | | | | |

Samples received on: Tuesday, September 23, 1997

RJ Lee Group, Inc.
Bay Area Lab

530 McCormick Street
San Leandro, CA 94577

Page: 2 of 18

Authorized Signature

Date

Scott Stotler, Geologist

Friday, September 26, 1997

Phone (510) 567-0480

Fax (510) 567-0488

Test Report-Environmental Health Sciences-AK

Polarized Light Analysis Results

Project AOC709250

| Sample Number / | | -----Asbestos-----Nonasbestos----- | | | | | | | | | | Run Date | | |
|---|---|------------------------------------|---------|-------------|---------------|-----------|------------|-----------|------|-------|--------|----------|----------|---------|
| Sample Appearance | Client Sample Number | Chrysotile | Amosite | Crocidolite | Anthophyllite | Tremolite | Actinolite | Cellulose | Wool | Glass | Fibers | Fibers | Material | Analyst |
| 1646748CPL | GH-997-13 | <1 % | - | - | - | - | - | 5 % | - | - | - | - | 95 % | 9/24/97 |
| White gypsum board, white mud, tan tape | | | | | | | | | | | | | | |
| Layer Content: | Mud: 2% Chrysotile; Other Layers: None Detected | | | | | | | | | | | | | |
| 1646749CPL | GH-997-14 | 35 % | - | - | - | - | - | <1 % | - | - | - | - | 65 % | 9/24/97 |
| Brown linoleum, brown mastic | | | | | | | | | | | | | | |
| Layer Content: | Linoleum: 35% Chrysotile; Mastic: 2% Chrysotile | | | | | | | | | | | | | |
| 1646750CPL | GH-997-15 | - | - | - | - | - | - | <1 % | - | - | - | - | 99+ % | 9/24/97 |
| Brown cove base mastic | | | | | | | | | | | | | | |
| NFM: Qtz, Carb, Binder, Opaq, Mica, Misc. Part. | | | | | | | | | | | | | | |
| Homogeneous | | | | | | | | | | | | | | |
| 1646751CPL | GH-997-16 | - | - | - | - | - | - | 30 % | - | - | - | - | 70 % | 9/24/97 |
| Black tar paper underlayment | | | | | | | | | | | | | | |
| NFM: Qtz, Tar, Carb, Opaq, Misc. Part. | | | | | | | | | | | | | | |
| Homogeneous | | | | | | | | | | | | | | |
| 1646752CPL | GH-997-17 | 85 % | - | - | - | - | - | 2 % | - | - | - | - | 13 % | 9/24/97 |
| White/tan insulation | | | | | | | | | | | | | | |
| NFM: Qtz, Carb, Opaq, Misc. Part. | | | | | | | | | | | | | | |
| Homogeneous | | | | | | | | | | | | | | |
| 1646753CPL | GH-997-18 | - | - | - | - | - | - | 40 % | - | - | - | - | 60 % | 9/24/97 |
| Black tar paper underlayment | | | | | | | | | | | | | | |
| NFM: Qtz, Tar, Carb, Opaq, Misc. Part. | | | | | | | | | | | | | | |
| Homogeneous | | | | | | | | | | | | | | |

Samples received on: Tuesday, September 23, 1997

RJ Lee Group, Inc.
Bay Area Lab

530 McCormick Street
San Leandro, CA 94577


Page: 3 of 18

Authorized Signature

Date

Scott Stotler, Geologist
Friday, September 26, 1997

Phone (510) 567-0480
Fax (510) 567-0488



Test Report-Environmental Health Sciences-AK

Polarized Light Analysis Results

Project AOC709250

| Sample Number / Sample Appearance | | Client Sample Number | Chrysotile | Amosite | Crocidolite | Anthophyllite | Tremolite | Actinolite | Cellulose | Wool | Glass | Fibers | Synthetic Fibers | Other Fibers | NonFibrous Material | Run Date | Analyst |
|---|--|---|------------|---------|-------------|---------------|-----------|------------|---|------|-------|--------|------------------|--------------|---------------------|----------|---------|
| 1646754CPL White insulation | | GH-997-19 | 95 % | - | - | - | - | - | <1 % | - | - | - | - | - | 5 % | 9/24/97 | SS |
| | | | | | | | | | NFM: Qtz, Carb, Opaq, Misc. Part. | | | | | | Homogeneous | | |
| 1646755CPL Grey linoleum, brown mastic | | GH-997-20 | - | - | - | - | - | - | 30 % | - | - | - | - | - | 70 % | 9/24/97 | SS |
| | | | | | | | | | NFM: Qtz, Carb, Binder, Opaq, Misc. Part. | | | | | | Non Homogeneous | | |
| 1646756CPL Brown cove base mastic | | GH-997-21 | - | - | - | - | - | - | <1 % | - | - | - | - | - | 99+ % | 9/24/97 | SS |
| | | | | | | | | | NFM: Qtz, Carb, Binder, Opaq, Misc. Part. | | | | | | Non Homogeneous | | |
| 1646757CPL Brown sheet vinyl, brown mastic | | GH-997-22 | 35 % | - | - | - | - | - | <1 % | - | - | - | - | - | 65 % | 9/24/97 | SS |
| Layer Content: | | Sheet Vinyl: 35% Chrysotile; Mastic: <1% Chrysotile | | | | | | | | | | | | | | | |
| 1646758CPL Brown cove base mastic | | GH-997-23 | - | - | - | - | - | - | <1 % | - | - | - | - | - | 99+ % | 9/24/97 | SS |
| | | | | | | | | | NFM: Qtz, Carb, Binder, Opaq, Misc. Part. | | | | | | Non Homogeneous | | |
| 1646759CPL Yellow insulation, brown mastic | | GH-997-24 | - | - | - | - | - | - | <1 % | 85 % | - | - | - | - | 15 % | 9/24/97 | SS |
| | | | | | | | | | NFM: Qtz, Carb, Binder, Opaq, Misc. Part. | | | | | | Non Homogeneous | | |

Samples received on: Tuesday, September 23, 1997

RJ Lee Group, Inc.
Bay Area Lab

530 McCormick Street
San Leandro, CA 94577


Page: 4 of 18

Authorized Signature

Date

Scott Stotler, Geologist
Friday, September 26, 1997

Phone (510) 567-0480
Fax (510) 567-0488



Test Report-Environmental Health Sciences-AK

Polarized Light Analysis Results

Project AOC709250

| | | Asbestos | | | | | Nonasbestos | | | | |
|--|----------------------|------------|---------|-------------|---------------|-----------|-------------|-----------|------|-------|--|
| Sample Number / Sample Appearance | Client Sample Number | Chrysotile | Amosite | Crocidolite | Anthophyllite | Tremolite | Actinolite | Cellulose | Wool | Glass | Fibers Synthetic Other NonFibrous Run Date |
| 1646760CPL Pink fiberglass insulation | GH-997-25 | - | - | - | - | - | - | 2 % | 80 % | - | 18 % 9/24/97 SS Homogeneous |
| NFM: Qtz, Carb, Binder, Opaq, Misc. Part. | | | | | | | | | | | |
| 1646761CPL Tan insulation | GH-997-26 | - | - | - | - | - | - | 95 % | - | - | 5 % 9/24/97 SS Homogeneous |
| NFM: Qtz, Carb, Opaq, Misc. Part. | | | | | | | | | | | |
| 1646762CPL Brown ceiling insulation | GH-997-27 | - | - | - | - | - | - | 80 % | - | - | 20 % 9/24/97 SS Homogeneous |
| NFM: Qtz, Tar, Carb, Opaq, Misc. Part. | | | | | | | | | | | |
| 1646763CPL Tan insulation | GH-997-28 | - | - | - | - | - | - | 98 % | - | - | 2 % 9/24/97 SS Homogeneous |
| NFM: Qtz, Carb, Opaq, Misc. Part. | | | | | | | | | | | |
| 1646764CPL Black tar paper | GH-997-29 | - | - | - | - | - | - | 50 % | - | - | 50 % 9/24/97 SS Homogeneous |
| NFM: Qtz, Tar, Carb, Opaq, Misc. Part. | | | | | | | | | | | |
| 1646765CPL Black roofing tar paper | GH-997-30 | - | - | - | - | - | - | 50 % | - | - | 50 % 9/24/97 SS Homogeneous |
| NFM: Qtz, Tar, Carb, Opaq, Mica, Misc. Part. | | | | | | | | | | | |

Samples received on: Tuesday, September 23, 1997

Authorized Signature

Date

Scott Stotler, Geologist

Friday, September 26, 1997


Phone (510) 567-0480

Fax (510) 567-0488

530 McCormick Street
San Leandro, CA 94577

Page: 5 of 18

RJ Lee Group, Inc.
Bay Area Lab



Test Report-Environmental Health Sciences-AK

Polarized Light Analysis Results

Project AOC709250

| Sample Number / | | Asbestos | | | | | | | | | | | Nonasbestos | | | |
|---|----------------------|------------|---------|-------------|---------------|-----------|------------|-----------|--------------|--------------|------------------|---------------------------|-------------|---------|--|--|
| Sample Appearance | Client Sample Number | Chrysotile | Amosite | Crocidolite | Anthophyllite | Tremolite | Actinolite | Cellulose | Mineral Wool | Glass Fibers | Synthetic Fibers | Other NonFibrous Material | Run Date | Analyst | | |
| 1646766CPL Brown paper duct insulation | GH-997-31 | - | - | - | - | - | - | 90 % | - | - | - | 10 % | 9/24/97 | SS | | |
| NFM: Qtz, Tar, Carb, Opaq, Misc. Part. Homogeneous | | | | | | | | | | | | | | | | |
| 1646767CPL Red/white floor tile, black mastic Layer Content: Tile: 5% Chrysotile; Mastic: None Detected | GH-997-32 | 5 % | - | - | - | - | - | <1 % | - | - | - | 95 % | 9/24/97 | SS | | |
| NFM: Qtz, Tar, Carb, Binder, Opaq, Misc. Part. Non Homogeneous | | | | | | | | | | | | | | | | |
| 1646768CPL Black roof tar paper | GH-997-33 | - | - | - | - | - | - | 30 % | - | - | - | 70 % | 9/24/97 | SS | | |
| NFM: Qtz, Tar, Carb, Opaq, Misc. Part. Homogeneous | | | | | | | | | | | | | | | | |
| 1646769CPL Tan ceiling insulation | GH-997-34 | - | - | - | - | - | - | 95 % | - | - | - | 5 % | 9/24/97 | SS | | |
| NFM: Qtz, Carb, Opaq, Misc. Part. Homogeneous | | | | | | | | | | | | | | | | |
| 1646770CPL Tan ceiling insulation | GH-997-35 | - | - | - | - | - | - | 95 % | - | - | - | 5 % | 9/24/97 | SS | | |
| NFM: Qtz, Carb, Opaq, Misc. Part. Homogeneous | | | | | | | | | | | | | | | | |
| 1646771CPL White celotex board ceiling | GH-997-36 | - | - | - | - | - | - | 85 % | - | - | - | 15 % | 9/24/97 | SS | | |
| NFM: Qtz, Carb, Binder, Opaq, Misc. Part. Homogeneous | | | | | | | | | | | | | | | | |

Samples received on: Tuesday, September 23, 1997

Authorized Signature

Date

Scott Stotler, Geologist
Friday, September 26, 1997

RJ Lee Group, Inc.
Bay Area Lab

530 McCormick Street
San Leandro, CA 94577

Phone (510) 567-0480
Fax (510) 567-0488

Test Report-Environmental Health Sciences-AK

Polarized Light Analysis Results

Project AOC709250

| -----Asbestos-----Nonasbestos----- | | | | | | | | | |
|---|----------------------|------------|---------|-------------|---------------|-----------|------------|-----------|---|
| Sample Number / Sample Appearance | Client Sample Number | Chrysotile | Amosite | Crocidolite | Anthophyllite | Tremolite | Actinolite | Cellulose | Mineral Fibrous Synthetic Other NonFibrous Run Date |
| 1646772CPL White celotex board ceiling | GH-997-37 | - | - | - | - | - | - | 85 % | 15 % 9/24/97 SS Homogeneous |
| 1646773CPL Grey window caulking | GH-997-38 | <1 % | - | - | - | - | - | <1 % | 99+ % 9/24/97 SS Homogeneous |
| 1646774CPL Black/grey roof patching | GH-997-39 | 10 % | - | - | - | - | - | <1 % | 90 % 9/24/97 SS Homogeneous |
| 1646775CPL Black roofing, silver paint | GH-997-40 | 1 % | - | - | - | - | - | 20 % | 79 % 9/26/97 SS Non Homogeneous |
| Layer Content: Silver Paint: 10% Chrysotile; Black Roofing: None Detected | | | | | | | | | |
| 1646776CPL Black/grey roof patching | GH-997-41 | 15 % | - | - | - | - | - | <1 % | 85 % 9/26/97 SS Homogeneous |
| 1646777CPL Brown floor tile, black mastic | GH-997-42 | 3 % | - | - | - | - | - | <1 % | 97 % 9/26/97 SS Non Homogeneous |
| Layer Content: Tile: 3% Chrysotile; Mastic: None Detected | | | | | | | | | |

Samples received on: Tuesday, September 23, 1997

Authorized Signature

Date

Scott Stotler, Geologist


Friday, September 26, 1997

RJ Lee Group, Inc.
Bay Area Lab

530 McCormick Street
San Leandro, CA 94577

Phone (510) 567-0480
Fax (510) 567-0488

Page: 7 of 18



Test Report-Environmental Health Sciences-AK

Polarized Light Analysis Results

Project AOC709250

-----Asbestos-----Nonasbestos-----

| Sample Number / Sample Appearance | Client Sample Number | Chrysotile | Amosite | Crocidolite | Anthophyllite | Tremolite | Actinolite | Cellulose | Wool | Glass | Fibers | Fibers | Other | NonFibrous | Run Date | Analyst |
|---|----------------------|------------|---------|-------------|---------------|-----------|------------|-----------|------|-------|--------|--------|-------|------------|----------|---------|
| 1646778CPL White gypsum, white mud, white tape Layer Content: Mud: 3% Chrysotile; Other Layers: None Detected | GH-997-43 | <1 % | - | - | - | - | - | 5 % | - | - | - | - | - | 95 % | 9/26/97 | SS |
| 1646779CPL Brown floor tile, black mastic Layer Content: Tile: 3% Chrysotile; Mastic: None Detected | GH-997-44 | 3 % | - | - | - | - | - | <1 % | - | - | - | - | - | 97 % | 9/26/97 | SS |
| 1646780CPL White gypsum, white mud, white tape Layer Content: Mud: 3% Chrysotile; Other Layers: None Detected | GH-997-45 | <1 % | - | - | - | - | - | 5 % | - | - | - | - | - | 95 % | 9/26/97 | SS |
| 1646781CPL Grey cement fiber board | GH-997-46 | 40 % | - | - | - | - | - | <1 % | - | - | - | - | - | 60 % | 9/26/97 | SS |
| 1646782CPL Grey window caulking | GH-997-47 | 1 % | - | - | - | - | - | <1 % | - | - | - | - | - | 99 % | 9/26/97 | SS |
| 1646783CPL Grey cement fiber board | GH-997-48 | 45 % | - | - | - | - | - | <1 % | - | - | - | - | - | 55 % | 9/26/97 | SS |

Samples received on: Tuesday, September 23, 1997

RJ Lee Group, Inc.
Bay Area Lab

RECEIVED
OCT 6 1997

Authorized Signature

Date

Scott Stotler, Geologist
Friday, September 26, 1997

Phone (510) 567-0480
Fax (510) 567-0488

530 McCormick Street
San Leandro, CA 94577

Page: 8 of 18

Test Report-Environmental Health Sciences-AK

Polarized Light Analysis Results

Project AOC709250

| | | Asbestos | | | | | | | | | | Nonasbestos | | | | |
|---|-------------------------------------|----------------------|------------|---------|-------------|---------------|-----------|------------|-----------|------|-------|-------------|--------|----------|---------|------|
| Sample Number / | Sample Appearance | Client Sample Number | Chrysotile | Amosite | Crocidolite | Anthophyllite | Tremolite | Actinolite | Cellulose | Wool | Glass | Fibers | Fibers | Material | Analyst | Date |
| 1646784CPL | White rope gasket | GH-997-49 | 90 % | - | - | - | - | - | 8 % | - | - | - | - | 2 % | 9/26/97 | SS |
| NFM: Qtz, Carb, Opaq, Misc. Part. | | | | | | | | | | | | | | | | |
| 1646785CPL | White gypsum, white mud, white tape | GH-997-50 | <1 % | - | - | - | - | - | 5 % | - | - | - | - | 95 % | 9/26/97 | SS |
| NFM: Qtz, Carb, Opaq, Gyp, Mica, Misc. Part. | | | | | | | | | | | | | | | | |
| Mud: 3% Chrysotile; Other Layers: None Detected | | | | | | | | | | | | | | | | |
| 1646786CPL | White furnace gasket | GH-997-51 | 80 % | - | - | - | - | - | 5 % | - | - | - | - | 15 % | 9/26/97 | SS |
| NFM: Qtz, Carb, Opaq, Gyp, Misc. Part. | | | | | | | | | | | | | | | | |
| Homogeneous | | | | | | | | | | | | | | | | |
| 1646787CPL | Black tar paper | GH-997-52 | - | - | - | - | - | - | 20 % | - | - | - | - | 80 % | 9/26/97 | SS |
| NFM: Qtz, Tar, Carb, Opaq, Misc. Part. | | | | | | | | | | | | | | | | |
| Homogeneous | | | | | | | | | | | | | | | | |
| 1646788CPL | Grey linoleum (tar paper) | GH-997-53 | - | - | - | - | - | - | 40 % | - | - | - | - | 60 % | 9/26/97 | SS |
| NFM: Qtz, Tar, Carb, Opaq, Misc. Part. | | | | | | | | | | | | | | | | |
| Homogeneous | | | | | | | | | | | | | | | | |
| 1646789CPL | Black tar paper | GH-997-54 | - | - | - | - | - | - | 20 % | - | - | - | - | 80 % | 9/26/97 | SS |
| NFM: Qtz, Tar, Carb, Opaq, Misc. Part. | | | | | | | | | | | | | | | | |
| Homogeneous | | | | | | | | | | | | | | | | |

Samples received on: Tuesday, September 23, 1997

Authorized Signature

Date

Scott Stotler, Geologist

Friday, September 26, 1997

RJ Lee Group, Inc.
Bay Area Lab

530 McCormick Street
San Leandro, CA 94577

Phone (510) 567-0480
Fax (510) 567-0488

Test Report-Environmental Health Sciences-AK

Polarized Light Analysis Results

Project AOC709250

| Sample Number / | | -----Asbestos----- | | | | | | | | | | | -----Nonasbestos----- | | | | |
|---|----------------------|--------------------|---------|-------------|---------------|-----------|------------|-----------|------|-------|--------|--------|-----------------------|---------|------|--|--|
| Sample Appearance | Client Sample Number | Chrysotile | Amosite | Crocidolite | Anthophyllite | Tremolite | Actinolite | Cellulose | Wool | Glass | Fibers | Fibers | Material | Analyst | Date | | |
| 1646790CPL | GH-997-55 | - | - | - | - | - | - | 30 % | - | - | - | - | 70 % | 9/26/97 | SS | | |
| Grey linoleum, black mastic | | | | | | | | | | | | | | | | | |
| 1646791CPL | GH-997-56 | 3 % | - | - | - | - | - | <1 % | - | - | - | - | 97 % | 9/26/97 | SS | | |
| Brown floor tile, brown mastic | | | | | | | | | | | | | | | | | |
| Layer Content: Tile: 3% Chrysotile; Mastic: None Detected | | | | | | | | | | | | | | | | | |
| 1646792CPL | GH-997-57 | - | - | - | - | - | - | <1 % | 99 % | - | - | - | 1 % | 9/26/97 | SS | | |
| Grey wool clg insulation | | | | | | | | | | | | | | | | | |
| 1646793CPL | GH-997-58 | <1 % | - | - | - | - | - | 20 % | - | - | - | - | 80 % | 9/26/97 | SS | | |
| Black roofing, silver coating | | | | | | | | | | | | | | | | | |
| Layer Content: Silver Coating: 10% Chrysotile; Roofing: None Detected | | | | | | | | | | | | | | | | | |
| 1646794CPL | GH-997-59 | - | - | - | - | - | - | <1 % | 99 % | - | - | - | 1 % | 9/26/97 | SS | | |
| Grey wool clg insulation | | | | | | | | | | | | | | | | | |
| 1646795CPL | GH-997-60 | - | - | - | - | - | - | <1 % | 99 % | - | - | - | 1 % | 9/26/97 | SS | | |
| Grey wool clg insulation | | | | | | | | | | | | | | | | | |

Samples received on: Tuesday, September 23, 1997

RJ Lee Group, Inc.
Bay Area Lab

530 McCormick Street
San Leandro, CA 94577

Page: 10 of 18

Authorized Signature

Date

Scott Stotler, Geologist

Friday, September 26, 1997

Phone (510) 567-0480

Fax (510) 567-0488

RECEIVED

OCT 6 1997

Test Report-Environmental Health Sciences-AK

Polarized Light Analysis Results

Project AOC709250

| Sample Number / | | Asbestos | | | | | | | | | | | Nonasbestos | | | | NonFibrous Run Date |
|---|----------------------|------------|---------|-------------|---------------|-----------|------------|-----------|------|-------|--------|--------|-------------|---------|--|--|---------------------|
| Sample Appearance | Client Sample Number | Chrysotile | Amosite | Crocidolite | Anthophyllite | Tremolite | Actinolite | Cellulose | Wool | Glass | Fibers | Fibers | Material | Analyst | | | |
| 1646796CPL | GH-997-61 | - | - | - | - | - | - | 30 % | - | - | - | - | 70 % | 9/26/97 | | | |
| Black tar paper siding, white coating | | | | | | | | | | | | | | | | | |
| NFM: Qtz, Tar, Carb, Binder, Opaq, Misc. Part. | | | | | | | | | | | | | | | | | |
| 1646797CPL | GH-997-62 | 95 % | - | - | - | - | - | <1 % | <1 % | - | - | - | 5 % | 9/26/97 | | | |
| White paper | | | | | | | | | | | | | | | | | |
| NFM: Qtz, Carb, Opaq, Misc. Part. | | | | | | | | | | | | | | | | | |
| 1646798CPL | GH-997-63 | 95 % | - | - | - | - | - | <1 % | - | - | - | - | 5 % | 9/26/97 | | | |
| White paper | | | | | | | | | | | | | | | | | |
| NFM: Qtz, Carb, Opaq, Misc. Part. | | | | | | | | | | | | | | | | | |
| 1646799CPL | GH-997-64 | - | - | - | - | - | - | 99 % | - | - | - | - | 1 % | 9/26/97 | | | |
| White cellulose board | | | | | | | | | | | | | | | | | |
| NFM: Qtz, Carb, Opaq, Misc. Part. | | | | | | | | | | | | | | | | | |
| 1646800CPL | GH-997-65 | - | - | - | - | - | - | 30 % | - | - | - | - | 70 % | 9/26/97 | | | |
| Grey linoleum (mastic not submitted) | | | | | | | | | | | | | | | | | |
| NFM: Qtz, Carb, Binder, Opaq, Misc. Part. | | | | | | | | | | | | | | | | | |
| 1646801CPL | GH-997-66 | <1 % | - | - | - | - | - | 90 % | - | - | - | - | 10 % | 9/26/97 | | | |
| White joint compound, cellulose bd | | | | | | | | | | | | | | | | | |
| NFM: Qtz, Carb, Opaq, Mica, Misc. Part. | | | | | | | | | | | | | | | | | |
| Joint Compound: 2% Chrysotile; Other Layer: None Detected | | | | | | | | | | | | | | | | | |
| Layer Content: | | | | | | | | | | | | | | | | | |
| Non Homogeneous | | | | | | | | | | | | | | | | | |
| Non Homogeneous | | | | | | | | | | | | | | | | | |

Samples received on: Tuesday, September 23, 1997

RJ Lee Group, Inc.
Bay Area Lab

530 McCormick Street
San Leandro, CA 94577

Page: 11 of 18

Authorized Signature

Date

Scott Stotler, Geologist

Friday, September 26, 1997

Phone (510) 567-0480

Fax (510) 567-0488

Test Report-Environmental Health Sciences-AK

Polarized Light Analysis Results

Project AOC709250

| -----Asbestos-----Nonasbestos----- | | | | | | | | | |
|--|----------------------|------------|---------|-------------|---------------|-----------|------------|-----------|--|
| Sample Number / Sample Appearance | Client Sample Number | Chrysotile | Amosite | Crocidolite | Anthophyllite | Tremolite | Actinolite | Cellulose | Mineral Fibrous Wool Glass Fibers Synthetic Other NonFibrous Run Date |
| 1646802CPL White gypsum wallboard, white joint compound Layer Content: Joint Compound: 2% Chrysotile; Other Layer: None Detected | GH-997-67 | <1 % | - | - | - | - | - | 5 % | 95 % 9/26/97 SS Non Homogeneous |
| 1646803CPL Grey linoleum, black mastic | GH-997-68 | - | - | - | - | - | - | 30 % | 70 % 9/26/97 SS Non Homogeneous |
| 1646804CPL Grey paper | GH-997-69 | - | - | - | - | - | - | 99 % | 1 % 9/26/97 SS Homogeneous |
| 1646805CPL Black paper | GH-997-70 | - | - | - | - | - | - | 40 % | 60 % 9/26/97 SS Homogeneous |
| 1646806CPL Brown paper | GH-997-71 | - | - | - | - | - | - | 95 % | 5 % 9/26/97 SS Homogeneous |
| 1646807CPL Red linoleum, black tar paper | GH-997-72 | - | - | - | - | - | - | 40 % | 60 % 9/26/97 SS Non Homogeneous |

Samples received on: Tuesday, September 23, 1997

RJ Lee Group, Inc.
Bay Area Lab

530 McCormick Street
San Leandro, CA 94577

Page: 12 of 18

Authorized Signature

Date

Scott Stotler, Geologist
Friday, September 26, 1997


Phone (510) 567-0480
Fax (510) 567-0488


Test Report-Environmental Health Sciences-AK

Polarized Light Analysis Results

Project AOC709250

| Sample Number / Sample Appearance | Client Sample Number | Asbestos-----Nonasbestos----- | | | | | | | | | | Run Date | | |
|--|----------------------|-------------------------------|---------|-------------|---------------|-----------|------------|-----------|------|-------|--------|----------|--------|----------------------------------|
| | | Chrysotile | Amosite | Crocidolite | Anthophyllite | Tremolite | Actinolite | Cellulose | Wool | Glass | Fibers | | Fibers | Material |
| 1646808CPL Black tar paper | GH-997-73 | - | - | - | - | - | - | 60 % | - | - | - | - | 40 % | 9/26/97 SS Homogeneous |
| NFM: Qtz, Tar, Carb, Opaq, Misc. Part. | | | | | | | | | | | | | | |
| 1646809CPL Brown linoleum, white paper (mastic not submitted) | GH-997-74 | - | - | - | - | - | - | 40 % | - | - | - | - | 60 % | 9/26/97 SS Non Homogeneous |
| NFM: Qtz, Carb, Binder, Opaq, Misc. Part. | | | | | | | | | | | | | | |
| 1646810CPL Black paper, horse hair | GH-997-75 | - | - | - | - | - | - | 60 % | - | - | - | - | 40 % | 9/26/97 SS Homogeneous |
| NFM: Qtz, Tar, Carb, Opaq, Misc. Part. | | | | | | | | | | | | | | |
| 1646811CPL Red linoleum, black mastic | GH-997-76 | - | - | - | - | - | - | 30 % | - | - | - | - | 70 % | 9/26/97 SS Non Homogeneous |
| NFM: Qtz, Tar, Carb, Opaq, Misc. Part. | | | | | | | | | | | | | | |
| 1646812CPL Black paper | GH-997-77 | - | - | - | - | - | - | 40 % | - | - | - | - | 60 % | 9/26/97 SS Homogeneous |
| NFM: Qtz, Tar, Carb, Opaq, Misc. Part. | | | | | | | | | | | | | | |
| 1646813CPL Green paper, brown wood, brown paper | GH-997-78 | - | - | - | - | - | - | 99 % | - | - | - | - | 1 % | 9/26/97 SS Non Homogeneous |
| NFM: Qtz, Carb, Opaq, Misc. Part. | | | | | | | | | | | | | | |


 Authorized Signature _____
 Date _____
 Scott Støder, Geologist
 Friday, September 26, 1997

DEC 16 1997


Samples received on: Tuesday, September 23, 1997

RJ Lee Group, Inc.
 Bay Area Lab

530 McCormick Street
 San Leandro, CA 94577
 Page: 13 of 18

Phone (510) 567-0480
 Fax (510) 567-0488

Test Report-Environmental Health Sciences-AK

Polarized Light Analysis Results

Project AOC709250

DEC- 5-97 SAT 4:22 PM RJ LEE GROUP, INC.

FAX NO. 5105670488

P. 2


| Sample Number / Sample Appearance | Client Sample Number | Asbestos | | | | Nonasbestos | | | |
|--|----------------------|------------|---------|-------------|---------------|-------------|------------|-----------|---|
| | | Chrysotile | Amosite | Crocidolite | Anthophyllite | Tremolite | Actinolite | Cellulose | Mineral Fibrous Synthetic Other NonFibrous Run Date |
| 1646808CPL Black tar paper | GH-997-73 | - | - | - | - | - | - | 60 % | 40 % 9/26/97 Homogeneous |
| 1646809CPL Brown linoleum, white paper (mastic not submitted) | GH-997-74 | - | - | - | - | - | - | 40 % | 60 % 9/26/97 Non Homogeneous |
| 1646810CPL Black paper, horse hair | GH-997-75 | - | - | - | - | - | - | 60 % | 40 % 9/26/97 Homogeneous |
| 1646811CPL Red linoleum, black mastic | GH-997-76 | - | - | - | - | - | - | 30 % | 70 % 9/26/97 Non Homogeneous |
| 1646812CPL Black paper | GH-997-77 | - | - | - | - | - | - | 40 % | 60 % 9/26/97 Homogeneous |
| 1646813CPL Green paper, brown wood, brown paper | GH-997-78 | - | - | - | - | - | - | 99 % | 1 % 9/26/97 Non Homogeneous |

Samples received on: Tuesday, September 23, 1997

RJ Lee Group, Inc.
Bay Area Lab

530 McCormick Street
San Leandro, CA 94577
Page: 13 of 18

Authorized Signature



Scott Stoder, Geologist
Friday, September 26, 1997

Date

Phone (510) 567-0480
Fax (510) 567-0488

Test Report-Environmental Health Sciences-AK

Polarized Light Analysis Results

Project AOC709250

| Sample Number / Sample Appearance | | Asbestos | | | | | | | | | | Nonasbestos | | | |
|---|-----------|------------|---------|-------------|---------------|-----------|------------|---|--------------|--------------|------------------|---------------------------|----------|-----------------|--|
| | | Chrysotile | Amosite | Crocidolite | Anthophyllite | Tremolite | Actinolite | Cellulose | Mineral Wool | Glass Fibers | Synthetic Fibers | Other NonFibrous Material | Run Date | Analyst | |
| 1646814CPL | GH-997-79 | - | - | - | - | - | - | 95 % | - | - | - | 5 % | 9/26/97 | SS | |
| Brown flooring | | | | | | | | NFM: Qtz, Carb, Binder, Opaq, Misc. Part. | | | | | | Homogeneous | |
| 1646815CPL | GH-997-80 | - | - | - | - | - | - | 40 % | <1 % | - | - | 60 % | 9/26/97 | SS | |
| Yellow linoleum, brown mastic, grey underlay-ment | | | | | | | | NFM: Qtz, Carb, Binder, Opaq, Misc. Part. | | | | | | Non Homogeneous | |
| 1646816CPL | GH-997-81 | - | - | - | - | - | - | 95 % | - | - | - | 5 % | 9/26/97 | SS | |
| Brown hardwood flooring | | | | | | | | NFM: Qtz, Carb, Binder, Opaq, Misc. Part. | | | | | | Homogeneous | |
| 1646817CPL | GH-997-82 | - | - | - | - | - | - | 40 % | - | - | - | 60 % | 9/26/97 | SS | |
| Brown linoleum, grey underlay-ment (mastic not submitted) | | | | | | | | NFM: Qtz, Carb, Binder, Opaq, Misc. Part. | | | | | | Non Homogeneous | |
| 1646818CPL | GH-997-83 | - | - | - | - | - | - | <1 % | 90 % | - | - | 10 % | 9/26/97 | SS | |
| Brown gasket | | | | | | | | NFM: Qtz, Carb, Opaq, Misc. Part. | | | | | | Homogeneous | |
| 1646819CPL | GH-997-84 | - | - | - | - | - | - | 40 % | - | - | - | 60 % | 9/26/97 | SS | |
| Brown linoleum, brown mastic, grey underlay-ment | | | | | | | | NFM: Qtz, Carb, Binder, Opaq, Misc. Part. | | | | | | Homogeneous | |

Samples received on: Tuesday, September 23, 1997

RJ Lee Group, Inc.
Bay Area Lab

530 McCormick Street
San Leandro, CA 94577

Page: 14 of 18

Authorized Signature

Date

Scott Stotler, Geologist

Friday, September 26, 1997

Phone (510) 567-0480
Fax (510) 567-0488



Test Report-Environmental Health Sciences-AK

Polarized Light Analysis Results

Project AOC709250

| Sample Number / Sample Appearance | | Client Sample Number | Chrysotile | Amosite | Crocidolite | Anthophyllite | Tremolite | Actinolite | Cellulose | Wool | Glass | Fibers | Fibers | Material | NonFibrous | Run Date | Analyst |
|--|--|----------------------|------------|---------|-------------|---------------|-----------|------------|--|------|-------|--------|--------|----------|------------|----------|-----------------|
| 1646820CPL | | GH-997-85 | - | - | - | - | - | - | 95 % | - | - | - | - | 5 % | | 9/26/97 | SS |
| Green/brown celotex bd (no joint compound) | | | | | | | | | NFM: Qtz, Carb, Binder, Opaq, Misc. Part. | | | | | | | | Homogeneous |
| 1646821CPL | | GH-997-86 | - | - | - | - | - | - | 95 % | - | - | - | - | 5 % | | 9/26/97 | SS |
| Green/brown celotex bd (no joint compound) | | | | | | | | | NFM: Qtz, Carb, Binder, Opaq, Misc. Part. | | | | | | | | Homogeneous |
| 1646822CPL | | GH-997-87 | - | - | - | - | - | - | 5 % | - | - | - | - | 95 % | | 9/26/97 | SS |
| White gypsum bd (no joint compound) | | | | | | | | | NFM: Qtz, Carb, Opaq, Gyp, Mica, Misc. Part. | | | | | | | | Homogeneous |
| 1646823CPL | | GH-997-88 | 25 % | - | - | - | - | - | 20 % | - | - | - | - | 55 % | | 9/26/97 | SS |
| Black tar roofing, grit surfacing | | | | | | | | | NFM: Qtz, Tar, Carb, Opaq, Misc. Part. | | | | | | | | Homogeneous |
| 1646824CPL | | GH-997-89 | - | - | - | - | - | - | 30 % | 20 % | - | - | - | 50 % | | 9/26/97 | SS |
| Yellow fiberglass, black vapor barrier | | | | | | | | | NFM: Qtz, Tar, Carb, Binder, Opaq, Misc. Part. | | | | | | | | Non Homogeneous |
| 1646825CPL | | GH-997-90 | - | - | - | - | - | - | 10 % | 70 % | - | - | - | 20 % | | 9/26/97 | SS |
| Yellow fiberglass, black vapor barrier | | | | | | | | | NFM: Qtz, Tar, Carb, Binder, Opaq, Misc. Part. | | | | | | | | Non Homogeneous |

Samples received on: Tuesday, September 23, 1997

Authorized Signature



RJ Lee Group, Inc.
Bay Area Lab

530 McCormick Street
San Leandro, CA 94577
Page: 15 of 18

Date

Seatt Stotler, Geologist

Friday, September 26, 1997

Phone (510) 567-0480
Fax (510) 567-0488

Test Report-Environmental Health Sciences-AK

Polarized Light Analysis Results

Project AOC709250

| Sample Number / Sample Appearance | Client Sample Number | Asbestos | | | | | | | | | | Nonasbestos | | | | NonFibrous Run Date |
|--|----------------------|------------|---------|-------------|---------------|-----------|------------|--|------|-------|--------|-------------|-------|----------|---------|---------------------|
| | | Chrysotile | Amosite | Crocidolite | Anthophyllite | Tremolite | Actinolite | Cellulose | Wool | Glass | Fibers | Fibers | Other | Material | Analyst | |
| 1646826CPL Black tar paper, grit surfacing | GH-997-91 | 20 % | - | - | - | - | - | 20 % | - | - | - | - | 60 % | 9/26/97 | SS | Homogeneous |
| | | | | | | | | NFM: Qtz, Tar, Carb, Opaq, Misc. Part. | | | | | | | | |
| 1646827CPL Yellow fiberglass, black vapor barrier | GH-997-92 | - | - | - | - | - | - | 20 % | 50 % | - | - | - | 30 % | 9/26/97 | SS | Non Homogeneous |
| | | | | | | | | NFM: Qtz, Tar, Carb, Binder, Opaq, Misc. Part. | | | | | | | | |
| 1646828CPL Black cloth, white insulation | GH-997-93 | - | - | - | - | - | - | 5 % | <1 % | - | - | - | 95 % | 9/26/97 | SS | Non Homogeneous |
| | | | | | | | | NFM: Qtz, Tar, Carb, Binder, Opaq, Misc. Part. | | | | | | | | |
| 1646829CPL Brown hardwood floor | GH-997-94 | - | - | - | - | - | - | 95 % | - | - | - | - | 5 % | 9/26/97 | SS | Homogeneous |
| | | | | | | | | NFM: Qtz, Carb, Binder, Opaq, Misc. Part. | | | | | | | | |
| 1646830CPL Brown hardwood floor, black mastic | GH-997-95 | - | - | - | - | - | - | 94 % | - | - | - | - | 6 % | 9/26/97 | SS | Non Homogeneous |
| | | | | | | | | NFM: Qtz, Tar, Carb, Binder, Opaq, Misc. Part. | | | | | | | | |
| 1646831CPL Black tar paper | GH-997-96 | - | - | - | - | - | - | 60 % | - | - | - | - | 40 % | 9/26/97 | SS | Homogeneous |
| | | | | | | | | NFM: Qtz, Tar, Carb, Opaq, Misc. Part. | | | | | | | | |

Samples received on: Tuesday, September 23, 1997

RJ Lee Group, Inc.
Bay Area Lab

530 McCormick Street
San Leandro, CA 94577
Page: 16 of 18

Authorized Signature

Date

Scott Stotler, Geologist
Friday, September 26, 1997

Phone (510) 567-0480
Fax (510) 567-0488

Test Report-Environmental Health Sciences-AK

Polarized Light Analysis Results

Project AOC709250

| -----Asbestos-----Nonasbestos----- | | | | | | | | | | | | | |
|--------------------------------------|----------------------|------------|---------|-------------|---------------|-----------|------------|-----------|---|-------|--------|---------------------------|------------------------------|
| Sample Number / Sample Appearance | Client Sample Number | Chrysotile | Amosite | Crocidolite | Anthophyllite | Tremolite | Actinolite | Cellulose | Wool | Glass | Fibers | Other NonFibrous Material | Run Date Analyst |
| 1646832CPL White window putty | GH-997-97 | - | - | - | - | - | - | <1 % | NFM: Qtz, Carb, Binder, Opaq, Misc. Part. | - | - | 99+ % | 9/26/97 SS Homogeneous |
| 1646833CPL White window putty | GH-997-98 | - | - | - | - | - | - | <1 % | NFM: Qtz, Carb, Binder, Opaq, Misc. Part. | - | - | 99+ % | 9/26/97 SS Homogeneous |
| 1646834CPL Black tar paper | GH-997-99 | - | - | - | - | - | - | 45 % | NFM: Qtz, Tar, Carb, Opaq, Misc. Part. | - | - | 55 % | 9/26/97 SS Homogeneous |
| 1646835CPL Brown cellulose board | GH-997-100 | - | - | - | - | - | - | 99 % | NFM: Qtz, Carb, Opaq, Misc. Part. | - | - | 1 % | 9/26/97 SS Homogeneous |
| 1646836CPL Grey cement fiberboard | GH-997-101 | 40 % | - | <1 % | - | - | - | <1 % | NFM: Qtz, Carb, Binder, Opaq, Misc. Part. | - | - | 60 % | 9/26/97 SS Homogeneous |
| 1646837CPL White pipe insulation | GH-997-102 | 90 % | - | - | - | - | - | 1 % | NFM: Qtz, Carb, Opaq, Misc. Part. | - | - | 9 % | 9/26/97 SS Homogeneous |

Samples received on: Tuesday, September 23, 1997

Authorized Signature

Date

Scott Stotler, Geologist

Friday, September 26, 1997

530 McCormick Street
San Leandro, CA 94577

RJ Lee Group, Inc.
Bay Area Lab

Phone (510) 567-0480
Fax (510) 567-0488

Test Report-Environmental Health Sciences-AK

Polarized Light Analysis Results

Project AOC709250

| | | Asbestos | | | | Nonasbestos | | | |
|-----------------------|----------------------|------------|---------|-------------|---------------|-------------|------------|-----------|-------------|
| Sample Number / | Client Sample Number | Chrysotile | Amosite | Crocidolite | Anthophyllite | Tremolite | Actinolite | Cellulose | Mineral |
| 1646838CPL | GH-997-103 | 40 % | - | - | - | - | - | - | Mineral |
| White pipe insulation | | | | | | | | | Fibrous |
| | | | | | | | | | Glass |
| | | | | | | | | | Fibers |
| | | | | | | | | | Other |
| | | | | | | | | | Fibrous |
| | | | | | | | | | Material |
| | | | | | | | | | Analyst |
| | | | | | | | | | SS |
| | | | | | | | | | Homogeneous |

NFM: Qtz, Carb, Opaq, Gyp, Misc. Part.

Samples received on: Tuesday, September 23, 1997

RJ Lee Group, Inc.
Bay Area Lab

530 McCormick Street
San Leandro, CA 94577

Page: 18 of 18

Authorized Signature

Date

Scott Stotler, Geologist
Friday, September 26, 1997
Phone (510) 567-0480
Fax (510) 567-0488

CHAIN OF CUSTODY RECORD/FIELD SURVEY DATA

Page 1 of 1

| | | | | | | | |
|--|--|---|--|--|--|------------------------------|--|
| FIELD COLLECTION DATE: 9-19-97 | | JOB #: 3968-01-02 | | MATERIAL TYPE: (Circle) ASBESTOS LEAD | | TOTAL QUANTITIES: 7 | |
| PROJECT NAME: Gov Hill Telephones EA2 | | | | BULK ANALYSIS REQUESTED: (Circle) PLM DUST / TEM BULK / LEAD TCLP / LEAD PPM | | | |
| FACILITY: Gov Hill Wireles Sta | | | | DISPOSAL: Routine | | TURNAROUND: 3 days | |
| SPECIAL INSTRUCTIONS: Fax w/COE | | | | | | | |
| COLLECTED BY (signature) Robert French | | SELECTED LABORATORY TCSY OPS/ICU FP Prop 307 | | COMMENTS: | | | |
| PRINTED NAME 1564 88IM-008 | | SAMPLES ACCEPTED BY 9/24/97 8:00 A | | | | | |
| CERT# AHERA# | | DATE/TIME 9/24/97 9:00 A | | | | | |
| SHIPPING METHOD Courier | | ANALYST'S SIGNATURE 9/24/97 9:00 A | | | | | |
| COURIER (signature) 9-23-97 6:30 pm | | DATE | | 117-0241 | | | |
| SAMPLE ID | | SAMPLE DESCRIPTION, (COLOR, MATERIAL TYPE, LAYERS, FRIABILITY) | | LOCATION/COMMENTS (INCLUDING PHOTO/REF) | | RESULTS | |
| 1. GH997-Q1 | | Red Brick Pattern 'Self-stic' 12"x12" tile | | Bldg 1 South Office Split from Sample 2 | | 2. Asbestos 5-10% Chrysotile | |
| MATERIAL CONDITION: GOOD FAIR POOR | | DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | | | | | |
| 2. GH997-Q2 | | Bldg Paper | | Exterior - under Bldg 1 siding, SE corner Split from Sample 8 | | None Detected | |
| MATERIAL CONDITION: GOOD FAIR POOR | | DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | | | | | |
| 3. GH997-Q3 | | Blown in Mixed Insul | | Above ceiling of kitchen Split from Sample 28 Bldg 1 | | None Detected | |
| MATERIAL CONDITION: GOOD FAIR POOR | | DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | | | | | |
| 4. GH997-Q4 | | Brown/Black/Reddish Tar Linoleum | | NO of Furrow Split from Sample 55 Bldg 2 | | None Detected | |
| MATERIAL CONDITION: GOOD FAIR POOR | | DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | | | | | |
| 5. GH997-Q5 | | Reddish Inte Backed linoleum w/ black tarpaper underlay | | Center West Room @ Door to NW Split from Sample 72 Bldg 3 | | None Detected | |
| MATERIAL CONDITION: GOOD FAIR POOR | | DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | | | | | |
| 6. GH997-Q6 | | Yellowish Inte backed linoleum w/ gray underlay | | West Side of S. Room Split from Sample 10 Bldg 3 | | None Detected | |
| MATERIAL CONDITION: GOOD FAIR POOR | | DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | | | | | |
| 7. GH997-Q7 | | | | | | | |
| MATERIAL CONDITION: GOOD FAIR POOR | | DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | | | | | |
| 8. | | | | | | | |
| MATERIAL CONDITION: GOOD FAIR POOR | | DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | | | | | |

****RETURN A SIGNED COPY OF THIS FORM WITH THE FINAL REPORT TO EHS-ALASKA****

FHS-9/95



SOLAR ENVIRONMENTAL SERVICES, INC.

1131 E. 76TH Ave., Ste. 102, Anchorage, Ak 99518

Phone (907) 349-7705/ Fax (907) 349-7944

NVLAP

Accredited Laboratory

U.S. Dept. of Commerce-NIST

CERTIFICATE OF ANALYSIS

CLIENT: Environmental Health Sciences-Ak
ATTN: Tom Swearingen, PhD
10298 Eagler River Road, Ste. 202
Eagle River, Ak 99577

CLIENT ORDER#: 191005
PROJECT NAME: Govt. Hill Telegraph EA2
PROJECT NO: 3968-01-02
REPORT NO: B97-0241
REPORT DATE: Sept. 25, 1997
COLLECTED BY: Robert French-Client
DATE SAMPLED: Sept. 19, 1997
DATE RECEIVED: Sept. 24, 1997
DATE ANALYZED: Sept. 24, 1997
ANALYZED BY: Tony Odsigue-SES

PAGE: 1 of 2

BULK ASBESTOS ANALYSIS REPORT POLARIZED LIGHT MICROSCOPY (PLM) EPA METHOD 600R93116

| LAB.# | CLIENT# | LOCATION/ DESCRIPTION/ (COLOR) | %ASBESTOS PRESENT | %OTHER FIBROUS MATERIALS | %NONFIBROUS MATERIALS |
|-------------|----------|---|----------------------|------------------------------------|--------------------------|
| 97531BO1146 | GH997-Q1 | Red-brick Pattern 12"x12" Bldg. 1 South Office (Red) | 5-10%Chrysotile | 1-3% Fibrous Glass | 82-91% |
| 97531BO1147 | GH997-Q2 | Bldg. Paper Exterior-under Bldg. siding SE Corner (Lt. brown) | None Detected | 90-92% Cellulose 3-5% Synthetic | 3-7% |
| 97531BO1148 | GH997-Q3 | Brown in mixed Insulation Above Ceiling of kitchen , bldg 1 (Lt. Cream) | None Detected | 90-95% Cellulose | 5-10% |
| 97531BO1149 | GH997-Q4 | Linoleum layer Brown/Black Reddish Tar Linoleum N. of Furnace Linoleum(Red/Black) | None Detected | 55-60%Cellulose | 40-45% |

All quantitations are based on visual estimation unless point counting method, per NESHAP 40 CFR Part 61, is requested by client. Test report relates only to the items tested and must not be used by client to claim product endorsement by NVLAP or any Agency of the U.S. Government. Test report must not be reproduced except in full without the approval of SES and subject to SES general terms and conditions. Small asbestos fibers may be missed by PLM Method due to resolution limitations of the optical microscope. Therefore, None Detected and <1% PLM results cannot be guaranteed. Transmission Electron Microscopy (TEM) is recommended for confirmation.

REVIEWED AND APPROVED BY: Gracita O. Torrijos, Chemist-I.H.

Date: 9/25/97



SOLAR ENVIRONMENTAL SERVICES, INC.

1131 E. 76TH Ave., Ste. 102, Anchorage, Ak 99518

Phone (907) 349-7705/ Fax (907) 349-7944

NVLAP

Accredited Laboratory

U.S. Dept. of Commerce-NIST

CERTIFICATE OF ANALYSIS

CLIENT: Environmental Health Sciences-Ak
ATTN: Tom Swearingen, PhD
10298 Eagler River Road, Ste. 202
Eagle River, Ak 99577

CLIENT ORDER#: 191005
PROJECT NAME: Govt. Hill Telegraph EA2
PROJECT NO: 3968-01-02
REPORT NO: B97-0241
REPORT DATE: Sept. 25, 1997
COLLECTED BY: Robert French-Client
DATE SAMPLED: Sept. 19, 1997
DATE RECEIVED: Sept. 24, 1997
DATE ANALYZED: Sept. 24, 1997
ANALYZED BY: Tony Odsigue-SES

PAGE: 2 of 2

BULK ASBESTOS ANALYSIS REPORT POLARIZED LIGHT MICROSCOPY (PLM) EPA METHOD 600R93116

| LAB.# | CLIENT# | LOCATION/ DESCRIPTION/ (COLOR) | %ASBESTOS PRESENT | %OTHER FIBROUS MATERIALS | %NONFIBROUS MATERIALS |
|---------------|------------|--|----------------------|------------------------------------|--------------------------|
| | | Mastic layer Brown/Black Reddish Tar-bldg. 2 Linoleum N. of Furnace (Red/Black) | None Detected | 3-5% Cellulose | 95-97% |
| 97531BO1150 | GH997-Q5 | Reddish linoleum with black tar paper Center W. Rm door to NW Bldg 3 (Red/Brown) | None Detected | 35-40% Cellulose | 60-65% |
| 97531BO1151 | GH997-Q6 | Yellowish Linoleum with gray underlay West side of S. Rm Bldg. 3 (Brown/Yellow/Gray) | None Detected | 65-70% Cellulose | 30-35% |
| 97531BO1147QC | GH997-02QC | QUALITY CONTROL | None Detected | 90-92% Cellulose 3-5% Synthetic | 3-7% |

All quantitations are based on visual estimation unless point counting method, per NESHAP 40 CFR Part 61, is requested by client. Test report relates only to the items tested and must not be used by client to claim product endorsement by NVLAP or any Agency of the U.S. Government. Test report must not be reproduced except in full without the approval of SES and subject to SES general terms and conditions. Small asbestos fibers may be missed by PLM Method due to resolution limitations of the optical microscope. Therefore, None Detected and <1% PLM results cannot be guaranteed. Transmission Electron Microscopy (TEM) is recommended for confirmation.

REVIEWED AND APPROVED BY:

Gracita O. Torrijos, Chemist-I.H.

Date: 7/25/97

APPENDIX B

Lead Field Data Sheets and Laboratory Reports



EHS ALASKA
INCORPORATED

lead

Environmental Health Sciences-Alaska, Inc.
10928 Eagle River Road, Suite 202, Eagle River, AK 99577-8052
(907) 694-1383 • (907) 694-1382 fax

ACC 709079


CHAIN OF CUSTODY RECORD/FIELD SURVEY DATA

Page 1 of 3

| | | | | | | | |
|--|--|---|--|---|--|----------------------|--|
| FIELD COLLECTION DATE: 9-19-97 | | JOB #: 3968-01-02 | | MATERIAL TYPE: (Circle) ASBESTOS <u>LEAD</u> | | TOTAL QUANTITIES: 31 | |
| PROJECT NAME: Gov. Hill Telegraph ^{E42} | | | | BULK ANALYSIS REQUESTED: (Circle) PLM / PLM DUST / TEM BULK / LEAD TCLP <u>LEAD PPM</u> | | | |
| FACILITY: Gov. Hill Wireless Sta | | | | DISPOSAL: Routine | | TURNAROUND: 3 days | |
| SPECIAL INSTRUCTIONS: | | | | | | | |
| COLLECTED BY (signature) <u>Robert French</u> PRINTED NAME Robert French CERT# 1564-88DUP-0028 SHIPING METHOD FEDERAL COURIER (signature) <u>[Signature]</u> DATE/TIME 9/22 | | SELECTED LABORATORY <u>R.J. Lee Gyr</u> SAMPLES ACCEPTED BY <u>[Signature]</u> DATE/TIME 9/23/97 9:30 ANALYST'S SIGNATURE DATE | | COMMENTS: | | | |
| SAMPLE ID | | SAMPLE DESCRIPTION, (COLOR, MATERIAL TYPE, LAYERS, FRIABILITY) | | LOCATION/COMMENTS (INCLUDING PHOTO/REF) | | RESULTS | |
| 1. GH997-L1 MATL. CONDITION: GOOD FAIR POOR | | Green Paint on Gyp DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | | SE corner of South office Bldg 1 | | 0.0603 % lead | |
| 2. GH997-L2 MATL. CONDITION: GOOD FAIR POOR | | Red paint, clear varnish on wood DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | | at Floor entry to South office, Bldg 1 | | 0.178% lead | |
| 3. GH997-L3 MATL. CONDITION: GOOD FAIR POOR | | Gray & white paint on wood DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | | South Room - at Rack supports Bldg 1 | | 0.0718% lead | |
| 4. GH997-L4 MATL. CONDITION: GOOD FAIR POOR | | White Paint on Gyp DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | | North Room walls NW corner Bldg 1 | | < 0.013% lead | |
| 5. GH997-L5 MATL. CONDITION: GOOD FAIR POOR | | White Paint on Gyp DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | | South Room ceiling, NW corner Bldg 1 | | 0.00514% lead | |
| 6. GH997-L6 MATL. CONDITION: GOOD FAIR POOR | | Green Paint on Wood DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | | Behind door in Toilet, West Wing Bldg 1 | | < 0.012% lead | |
| 7. GH997-L7 MATL. CONDITION: GOOD FAIR POOR | | Green Paint on Gyp DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | | Behind door in Toilet, West Wing Bldg 1 | | < 0.00558% lead | |
| 8. GH997-L8 MATL. CONDITION: GOOD FAIR POOR | | Exterior White Paint on wood DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | | SW corner of West Wing Bldg 1 | | 11.6% lead | |

RETURN A SIGNED COPY OF THIS FORM WITH THE FINAL REPORT TO EHS-ALASKA

EHS-9/95




EHS ALASKA
INCORPORATED

Environmental Health Sciences-Alaska, Inc.
10928 Eagle River Road, Suite 202, Eagle River, AK 99577-8052
(907) 694-1383 • (907) 694-1382 fax

FIELD SURVEY DATA (continued)

Page 2 of 3

| PROJECT NAME: <u>Gov Hill Telegraph EA2</u> | | FACILITY: <u>Gov. Hill Wireless Sta</u> | |
|---|--|--|-----------------------------|
| JOB NUMBER: <u>3968-01-02</u> | | DATE: <u>9-19-97</u> | COLLECTED BY: <u>French</u> |
| SAMPLE ID | SAMPLE DESCRIPTION, (COLOR, MATERIAL TYPE, LAYERS, FRIABILITY) | LOCATION/COMMENTS (INCLUDING PHOTO/REF) | RESULTS |
| GH997-L9 MATL. CONDITION: GOOD FAIR POOR | Exterior Green trim Paint on Wood DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | NW corner of West wing, Bldg 1 | 13.8 % lead |
| GH997-L10 MATL. CONDITION: GOOD FAIR POOR | White Paint on Dust DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | above Furnace Bldg 1 | 7.48 % lead |
| GH997-L11 MATL. CONDITION: GOOD FAIR POOR | White + Silver paint on Dust DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | at branch to South wing 145 Bldg 1 | 0.459 % lead |
| GH997-L12 MATL. CONDITION: GOOD FAIR POOR | White + Silver paint w/ silvery metal DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | at joints of branch to south wing Bldg 1 | 27.7 % lead |
| GH997-L13 MATL. CONDITION: GOOD FAIR POOR | Greenish paint on Gyp DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Center of N. wall Bldg 2 | 0.0373 % lead |
| GH997-L14 MATL. CONDITION: GOOD FAIR POOR | Greenish paint on Wood Window trim DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | NE window Frame Bldg 2 | 0.206 % lead |
| GH997-L15 MATL. CONDITION: GOOD FAIR POOR | Gray + Blue Floor Paint on tar linoleum DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Furnace Rm Floor Bldg 2 | 0.670 % lead |
| GH997-L16 MATL. CONDITION: GOOD FAIR POOR | White ceiling Paint DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | At Paper Joint Stage Center Bldg 2 | 0.0469 % lead |
| GH997-L17 MATL. CONDITION: GOOD FAIR POOR | off green paint on ply DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Ext central Rm, S wall Bldg 3 | 2.01 % lead |
| GH997-L18 MATL. CONDITION: GOOD FAIR POOR | off white dy paint on ply DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | Ext central Rm, Center Bldg 3 | 0.0714 % lead |
| GH997-L19 MATL. CONDITION: GOOD FAIR POOR | off green paint on ply cellulose b'd DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | NE Room, East wall Bldg 3 | 1.36 % lead |
| GH997-L20 MATL. CONDITION: GOOD FAIR POOR | off green paint on wood DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | NE Rm, at window trim Bldg 3 | 3.38 % lead |



EHS ALASKA
INCORPORATED

Lead

Environmental Health Sciences-Alaska, Inc.
10928 Eagle River Road, Suite 202, Eagle River, AK 99577-8052
(907) 694-1383 • (907) 694-1382 fax

FIELD SURVEY DATA (continued)

Page 3 of 3

| PROJECT NAME: <u>Gov Hill Telegraph EA-2</u> | | FACILITY: <u>Gov Hill Wireless Sta</u> | |
|--|--|--|-----------------------------|
| JOB NUMBER: <u>3968-01-02</u> | | DATE: <u>9-20-97</u> | COLLECTED BY: <u>French</u> |
| SAMPLE ID | SAMPLE DESCRIPTION, (COLOR, MATERIAL TYPE, LAYERS, FRIABILITY) | LOCATION/COMMENTS (INCLUDING PHOTO/XREF) | RESULTS |
| GH997-L21 | White paint on off ^{cellulose} ply ^{ply} | Center of NW room Bldg 3 | 0.0999% lead |
| MATL. CONDITION: GOOD FAIR POOR | DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | | |
| GH997-L22 | off green on wood | Center West Room on Base ^{Thin} Base Bldg 3 | 0.523% lead |
| MATL. CONDITION: GOOD FAIR POOR | DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | | |
| GH997-L23 | off green on wood | -Former ext trim? 1x2 T+G Bldg 3 | 0.651% lead |
| MATL. CONDITION: GOOD FAIR POOR | DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | | |
| GH997-L24 | Black + Lt green on wood | Center West Room at base trim Bldg 3 | 0.464% lead |
| MATL. CONDITION: GOOD FAIR POOR | DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | | |
| GH997-L25 | off green + white on cellulose Bd | Center West Room Bldg 3 | 0.495% lead |
| MATL. CONDITION: GOOD FAIR POOR | DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | | |
| GH997-L26 | Cream + Brown Paint on wood | 3/4" vert. groove - former NW corner of Center West Rm Bldg 3 | 0.287% lead |
| MATL. CONDITION: GOOD FAIR POOR | DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | | |
| GH997-L27 | White exterior Paint on wood | Near South window west side - orig. Bldg 3 | 9.56% lead |
| MATL. CONDITION: GOOD FAIR POOR | DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | | |
| GH997-L28 | Green Ext. Trim Paint. on wood | Sill of N. window, west side, orig. bldg. Bldg 3 | 13.9% lead |
| MATL. CONDITION: GOOD FAIR POOR | DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | | |
| GH997-L29 | White + green Flaky Paint | Conc. N. wall Bsmt Bldg 3 | 4.29% lead |
| MATL. CONDITION: GOOD FAIR POOR | DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | | |
| GH997-L30 | Gray Paint on wood | Ceiling of West Bsmt Bldg 3 | 3.68% lead |
| MATL. CONDITION: GOOD FAIR POOR | DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | | |
| GH997-L31 | White paint on wood | Center wall of Bsmt Bldg 3 | 5.16% lead |
| MATL. CONDITION: GOOD FAIR POOR | DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | | |
| MATL. CONDITION: GOOD FAIR POOR | DAMAGE POTENTIAL: (LO, MED, HI) WATER: AIR: VIBRATION: CONTACT: | | |

RJ Lee Group, Inc.

350 Hochberg Road Monroeville, PA 15146
Phone (412) 325-1776 Fax (412) 733-1799

LABORATORY REPORT


Environmental Health Sciences - Alaska, Inc.
10928 Eagle River Road, Suite 202
Eagle River, AK. 99577-8052

Attention: Robert French
(907) 694-1383 FAX (907) 694-1382

Analysis: Lead in Paint - FLAA
Method: EPA SW846-7420

RJ Lee Group Job No.: ACC709079
Samples Received: 23-Sep-97
Report Date: 26-Sep-97
Client Project: 3968-01-02
Gov. Hill Telegraph EAZ
Southall-Fairbanks

| Sample Identification | | Lead | |
|-----------------------|--------------|-------------------|----------------------|
| | | Weight Percent | Parts per Million |
| Client | RJ Lee Group | | |
| GH997-L1 | 0209137 | 0.0603 | 603 |
| GH997-L2 | 0209138 | 0.178 | 1,780 |
| GH997-L3 | 0209139 | 0.0718 | 718 |
| GH997-L4 | 0209140 | < 0.013 | < 130 |
| GH997-L5 | 0209141 | 0.00514 | 51.4 |
| GH997-L6 | 0209142 | < 0.012 | < 120 |
| GH997-L7 | 0209143 | < 0.0055 | < 55 |
| GH997-L8 | 0209144 | 11.6 | 116,000 |
| GH997-L9 | 0209145 | 13.8 | 138,000 |
| GH997-L10 | 0209146 | 7.48 | 74,800 |
| GH997-L11 | 0209147 | 0.459 | 4,590 |
| GH997-L12 | 0209148 | 27.7 | 277,000 |
| GH997-L13 | 0209149 | 0.0373 | 373 |
| GH997-L14 | 0209150 | 0.206 | 2,060 |
| GH997-L15 | 0209151 | 0.670 | 6,700 |
| GH997-L16 | 0209152 | 0.0469 | 469 |
| GH997-L17 | 0209153 | 2.01 | 20,100 |
| GH997-L18 | 0209154 | 0.0714 | 714 |
| GH997-L19 | 0209155 | 1.36 | 13,600 |



Authorized Signature: *Brandon J. Miller*
Date: 9-26-97

AIHA ELLAP #8204
CA ELAP #1970
PA DEP #02-396

Monroeville, PA - San Leandro, CA - Washington, DC - Houston, TX

RJ Lee Group, Inc.

350 Hochberg Road Monroeville, PA 15146
Phone (412) 325-1776 Fax (412) 733-1799

LABORATORY REPORT


Environmental Health Sciences - Alaska, Inc.
10928 Eagle River Road, Suite 202
Eagle River, AK. 99577-8052

Attention: Robert French
(907) 694-1383 FAX (907) 694-1382

Analysis: Lead in Paint - FLAA
Method: EPA SW846-7420

RJ Lee Group Job No.: ACC709079
Samples Received: 23-Sep-97
Report Date: 26-Sep-97
Client Project: 3968-01-02
Gov. Hill Telegraph EAZ
Southall-Fairbanks

| Sample Identification | | Lead | |
|-----------------------|--------------|-------------------|----------------------|
| Client | RJ Lee Group | Weight Percent | Parts per Million |
| GH997-L20 | 0209156 | 3.38 | 33,800 |
| GH997-L21 | 0209157 | 0.0999 | 999 |
| GH997-L22 | 0209158 | 0.523 | 5,230 |
| GH997-L23 | 0209159 | 0.651 | 6,510 |
| GH997-L24 | 0209160 | 0.464 | 4,640 |
| GH997-L25 | 0209161 | 0.495 | 4,950 |
| GH997-L26 | 0209162 | 0.287 | 2,870 |
| GH997-L27 | 0209163 | 9.56 | 95,600 |
| GH997-L28 | 0209164 | 13.9 | 139,000 |
| GH997-L29 | 0209165 | 4.29 | 42,900 |
| GH997-L30 | 0209166 | 3.68 | 36,800 |
| GH997-L31 | 0209167 | 5.16 | 51,600 |



These results are submitted pursuant to RJ Lee Group's current terms and conditions of sale, including the company's standard warranty and limitation of liability provisions. No responsibility or liability is assumed for the manner in which the results are used or interpreted. Unless notified in writing to return the samples covered by this report, RJ Lee Group will store the samples for a period of ninety (90) days before discarding. A shipping and handling fee will be assessed for the return of any samples.

Alan M. Levine, Manager ☐ Kimberly S. DiNatale, Scientist ☐ William E. Alexander, Assistant Chemist ☐
Brandon J. Miller, Assistant Scientist ☒ Please direct inquiries to Barbara A. Smith in Client Services.


AIHA ELLAP #8204
CA ELAP #1970
PA DEP #02-396

Authorized Signature Brandon J. Miller
Date 9-26-97


Monroeville, PA - San Leandro, CA - Washington, DC - Houston, TX

APPENDIX C

Floor Plans with Sample Locations



1 FLOOR PLAN, BUILDING 1
1/8"=1'0"



KEY PLAN


LEGEND

● GH997-XX ASBESTOS SAMPLE LOCATIONS

▲ GH997-LXX LEAD SAMPLE LOCATIONS


**GOV. HILL WIRELESS STATION
"TEE SHAPED", BLDG. NO.1
ANCHORAGE, ALASKA
HAZARDS SURVEY**

| | |
|-------------|------------|
| PROJECT NO. | 3968-01-02 |
| DESIGNED: | RAF |
| DRAWN: | WGB |
| CHECKED: | TBS |
| SCALE: | 1/8"=1' 0" |
| DWG. TITLE: | SURVEY |
| JOB No. | 3968-01-02 |
| DATE: | 12/11/97 |



LEGEND

- GH997-XX ASBESTOS SAMPLE LOCATIONS
- ▲ GH997-LXX LEAD SAMPLE LOCATIONS



KEY PLAN


1 FLOOR PLAN, BUILDING 2
B2 1 1/4"=1' 0"



**GOV. HILL WIRELESS STATION
BUILDING NO. 2
ANCHORAGE, ALASKA
HAZARDS SURVEY**

PROJECT NO.
3968-01-02
DESIGNED:
RAF
DRAWN:
WGB
CHECKED:
TBS
SCALE:
1/4"=1' 0"
DWG. TITLE:
SURVEY
JOB No.
3968-01-02
DATE:
12/11/97

B-2




LEGEND

● GH997-XX ASBESTOS SAMPLE LOCATIONS

▲ GH997-LXX LEAD SAMPLE LOCATIONS

1 FLOOR PLAN, BUILDING 3
 3A 1 3/16"=1'0"



**GOV. HILL WIRELESS STATION
 BUILDING NO. 3
 ANCHORAGE, ALASKA
 HAZARDS SURVEY**

PROJECT NO.
3968-01-02

DESIGNED:
RAF

DRAWN:
WGB


CHECKED:
TBS

SCALE:
3/16"=1' 0"



DWG. TITLE:
SURVEY

JOB No.
3968-01-02

DATE:
12/11/97



1 BASEMENT FLOOR PLAN, BUILDING 3
B-3B 1 1/4"=1'0"



KEY PLAN

LEGEND

- GH997-XX ASBESTOS SAMPLE LOCATIONS
- ▲ GH997-LXX LEAD SAMPLE LOCATIONS

APPENDIX D

Photographs of Potentially Hazardous Materials



Plate 1 Looking south in north room of Building 1. Gypsum wall board walls and ceiling without joint compound. Note ducts exposed with lead seal at seams, and concealed ducts in south room. South room has gypsum wall board walls and ceiling with asbestos-containing joint compound, and fluorescent light fixtures with PCB Ballasts.



Plate 2 Note debris and fungal growth in crawl space of west wing of Building 1.



Plate 3 White asbestos-containing pipe insulation debris under central crawl space of west wing of Building 1. Note copper pipe replaced insulated steel pipe.



Plate 4 Asbestos-containing gray fibrous patching on aluminum roofing of Building 1.



Plate 5 Cement asbestos board behind and below furnace in Building 2. Note rust stains on flooring and wet stains due to water leakage around furnace chimney.



Plate 6 Asbestos-containing gasket in return air plenum of furnace in Building 2.



Plate 7 White asbestos-containing pipe insulation in crawl space of Building 2. Note wet floor beams, leaves blown into crawl space through wood skirting, and fungal growth.



Plate 8 Asbestos-containing white paper in attic of Building 2.



Plate 9 South room of Building 3. Note furnace with attached gas line and abandoned oil piping and filter. Note fluorescent lights with PCB-containing ballasts and shelved cabinet with cement asbestos board lining.



Plate 10 Peeling paint in bathroom of Building 3.



Plate 11 Exterior wall, west central room of Building 3. Note floor dropped 4 inches, exposing horse hair and tar paper between layers of wood. Note dry rot.



Plate 12 Crawl space from access hatch at stairs to basement, Building 3. Note moisture drops and fungal growth on wood structure.



Plate 13 Damaged white asbestos-containing pipe insulation in basement of Building 3.



Plate 14 Asbestos-containing grit surfaced roofing of original section of Building 3. Note lead flashing on plumbing vent pipe and "new" rafters laid on "old" roofing.