

Bear Valley Community Council

1. Hillside LRSA's Road and Drainage Rehab
2. Heights Hill Surface Rehab/Subdrain - South of Clarks Road
3. Clarks Road Rut Repair
4. Clarks Road Drainage - Severely damaged culvert at the AT&T driveway causes severe glaciations each winter, also at Hosken's Road
5. Hillside District Plan for Drainage
6. New DeArmoun Road Fire Station #19 Land Acquisition
7. Hillside District Plan for Transportation
8. Mountain Air/Hillside Drive Extension
9. Abbott Road/Hillside Drive Trail - Rabbit Creek Road to Hillside Drive