


FAR NORTH BICENTENNIAL PARK





CLASS 1 FEATURES

- Tread intermittent and indistinct.
- Obstacles continuous.
- Constructed features minimal to non-existent.
- No destination signs present-limited to regulation, junction, and resource protection.

CLASS 2 FEATURES


- Tread discernible and continuous, but narrow and rough.
- Obstacles occasionally present.
- Structures are of limited size, scale and numbers.
- Minimal signage for basic direction, generally limited to regulation and resource protection.



TRAIL CLASS 3





TRAIL CLASS 4

FAR NORTH BICENTENNIAL PARK



CLASS 4 FEATURES

- Tread is wide and relatively smooth with few irregularities.
- Few or no obstacles exist, grades typically less than 12%, vegetation cleared outside of trailway.
- Constructed features/structures are frequent and substantial. Substantial trail bridges are appropriate at water crossings.
- Wide variety of signs present-informational and possibly interpretive.



CLASS 3 FEATURES

- Tread obvious and continuous.
- Obstacles infrequent. Vegetation cleared outside of trailway.
- Trail structures (walls, steps, drainage, raised trail, boardwalk) may be common and substantial.
- Directional signs at trail junctions.



TRAIL CLASS 5

FAR NORTH BICENTENNIAL PARK

CLASS 5 FEATURES

- Tread of trail is commonly hardened with asphalt or other imported material.
- No obstacles, grades typically less than 8% for accessibility.
- Constructed features/structures are frequent or continuous - curbing, handrails, trailside amenities, and boardwalks.
- Wide variety of signage - informational and interpretive.

